



Final Report for

February 25, 2021

Elinor Lake South Dam 2020 Dam Safety Review Report


For Regional District of Okanagan-Similkameen

HATCH

Report

Elinor Lake South Dam - 2020 Dam Safety Review Report

H362819-00000-228-230-0004



				<i>Shaun Murphy</i>	
2021-02-25	0	Approved for Use	S. Murphy/ P. Ashayer	D. Bonin	A. Pashan
DATE	REV.	STATUS	PREPARED BY	CHECKED BY	APPROVED BY
				Discipline Lead	Functional Manager

Disclaimer

The Naramata Dam – 2020 Dam Safety Review report and all associated reference files have been prepared by Hatch Ltd. for the sole and exclusive use of the Regional District of Okanagan-Similkameen (RDOS) (the “Client”) for the purpose of assisting the management of the Client in making decisions with respect to this structure. Any use which a third party makes of this report and all associated reference files, or any reliance on or decisions to be made based on it, are the responsibility of such third parties. Hatch accepts no responsibility or liability for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

This report contains opinions, conclusions and recommendations made by Hatch, using its professional judgment and reasonable care. Use of or reliance upon this report by the Client is subject to the following conditions:

- a) The report and associated reference files being read in the context of and subject to the terms of contract RDOS-20-PW-04 between Hatch Ltd. and the Client dated May 8, 2020 (the “Agreement”), including any methodologies, procedures, techniques, assumptions and other relevant terms or conditions that were specified or agreed therein.
- b) The report being read as a whole, with sections or parts hereof read or relied upon in context.
- c) The conditions of Elinor Lake South Dam may change over time or may have already changed due to natural forces or human intervention, and Hatch takes no responsibility for the impact that such changes may have on the accuracy or validity or the observations, conclusions and recommendations set out in this report.
- d) The report is based on information made available to Hatch by the Client or by certain third parties; and unless stated otherwise in the Agreement, Hatch has not verified the accuracy, completeness or validity of such information, makes no representation regarding its accuracy and hereby disclaims any liability in connection therewith.

Table of Contents

Disclaimer	i
Executive Summary	vi
1. Introduction	1
1.1 DSR Report Purpose and Scope	1
1.2 Previous Dam Safety Reviews	1
1.3 Objective	1
2. Description of Development	2
2.1 General	2
2.2 Site Description	3
2.2.1 Instrumentation	4
2.2.2 Dam and Reservoir Summary Information	4
2.3 History of Dam and Reservoir	4
3. Dam Safety Review Methodology	6
4. Data Collection and Review	7
4.1 Existing Information	7
4.2 Data Gaps	9
5. Site Inspection and Staff Interviews	11
5.1 General	11
5.1.1 Freeboard	13
5.2 Elinor Lake South Earthfill Dam	13
5.3 Spillway	14
5.4 Low Level Outlet Intake Structure	15
5.5 Low Level Outlet Structure	16
6. Consequences of Dam Failure and Dam Classification	17
6.1 Background Information	17
6.2 Previous Work by Others	19
6.3 Recommended Classification	19
7. Dam Safety Analyses	21
7.1 Failure Modes and Effects Analysis	21
7.2 Hydrotechnical Assessment	25
7.2.1 Review of Hydrological Studies	25
7.2.2 Flood Operating Rules	26
7.2.3 Discharge Capacity	26
7.2.3.1 Low Level Outlet	26
7.2.3.2 Spillway	27

7.2.4	Flood Passage Capability	28
7.2.5	Freeboard	28
7.2.6	Riprap	32
7.2.7	Ice and Debris	33
7.3	Structural Assessment	33
7.3.1	General	33
7.4	Geotechnical Assessment	34
7.4.1	Geology	34
7.4.2	Seismicity	34
7.4.3	Preliminary and Supplementary Field Investigations	35
7.4.3.1	Embankment Dam	35
7.4.3.2	Spillway	36
7.4.3.3	Foundation	37
7.4.3.4	Riparian Conduit	37
7.4.4	Geotechnical Seepage and Stability Assessment	37
7.4.4.1	Material Properties	38
7.4.4.2	Stability Criteria	38
7.4.4.3	Model Geometry	39
7.4.4.4	Seepage Analysis	40
7.4.4.5	Stability Analysis	42
7.4.5	Geotechnical Considerations	44
7.4.5.1	Liquefaction Potential	44
7.4.5.2	Post-seismic	44
7.4.5.3	Internal Stability and Material Compatibility	44
7.4.5.4	Instrumentation	44
7.4.5.5	Piping Potential	45
7.4.6	Geotechnical Assessment Conclusions	53
7.5	Mechanical Assessment	54
8.	Public Safety and Security	55
8.1	Site Observations	55
8.2	Public Safety Management Plan Audit	55
8.2.1	General	55
8.2.2	Riparian Conduit Structure	56
8.2.3	Spillway	56
8.3	Recommendations	56
9.	Dam Safety Management	57
9.1	Policy Development	59
9.2	Planning	60
9.3	Implementation	60
9.4	Checking and Reviewing	60
9.5	Corrective Actions	61
9.6	Reporting	61
9.7	Supporting Processes	62
9.7.1	Training and Qualification	62
9.7.2	Program Communication	62

9.7.3 Record Keeping and Management	62
9.8 Recommendations	63
10. Operations, Maintenance and Surveillance	64
10.1 Operation.....	64
10.1.1 Normal Operations	64
10.1.2 Flood Operations.....	65
10.1.3 Emergency Operations.....	65
10.2 Maintenance	66
10.3 Surveillance	66
10.4 Recommendations	67
11. Dam Emergency Plan.....	68
11.1 Recommendations	69
12. Dam Safety Expectations and Deficiencies	70
12.1 Dam Safety Review Assurance Statement	70
13. Conclusions and Recommendations	76
14. References.....	80

List of Tables

Table 2-1: Key Dimensions of Elinor Lake South Dam	4
Table 4-1: Existing Information Summary.....	7
Table 6-1: Consequence Classification Guide (B.C. Dam Safety Regulation, Water Sustainability Act Dam Safety Regulation 40/2016).....	18
Table 6-2: B.C. Dam Safety Regulation Downstream Dam Failure Consequence Classification (DFCC) Guide	19
Table 7-1: Hazard and Failure Modes Matrix for Elinor South Dam	23
Table 7-2: Flood Frequency Analysis	25
Table 7-3: PMF Peak Flows.....	26
Table 7-4: Elinor South Dam Effective Fetch Calculations	29
Table 7-5: Wind Velocities (km/h)	30
Table 7-6: Elinor South Dam Freeboard Assessment Results (CEM)	31
Table 7-7: CEM Riprap Requirements	32
Table 7-8: National Building Code of Canada (NBCC) Seismic Hazard	35
Table 7-9: Material Permeabilities	38
Table 7-10: Material Properties – Mohr-Coulomb Strength Parameters	38
Table 7-11: Required Minimum Factors of Safety.....	39
Table 7-12: Elinor Lake South Dam Selected Section Properties.....	40
Table 7-13: Results for Seepage Analyses.....	41
Table 7-14: Summary of Allowable Exit Gradients and Factors of Safety.....	41
Table 7-15: Loading Conditions Elinor Lake South Dam Section	42
Table 7-16: Results of Stability Analyses	43
Table 7-17: Foster and Fell [2000] Coefficients for Piping through the Elinor South Embankment Dam ..	46

Table 7-18: Foster and Fell [2000] Coefficients for Piping through Foundation of the Elinor South Embankment Dam	47
Table 7-19: Foster and Fell [2000] Coefficients for Piping of Embankment into Foundation of the Elinor South Embankment Dam	48
Table 12-1: Definition of Deficiencies and Non-Conformances [FLNRO, 2015].....	70
Table 12-2: Dam Safety Expectations	71
Table 13-1: Summary of Dam Safety Recommendations	77

List of Figures

Figure 2-1: Naramata Dams Location Map.....	2
Figure 2-2: Elinor Lake South Dam Major Component Layout	3
Figure 5-1: Elinor Lake South Dam Site Plan and Topography (Okanagan Survey, 2012)	12
Figure 7-1: Elinor South Dam Spillway Stage-Discharge Curve.....	27
Figure 7-2: Typical Cross Section of the Elinor South Embankment Dam.....	36
Figure 7-3: Spillway Plan at Elinor South Dam Site – (Okanagan Survey, 2012).....	37
Figure 7-4: Location of Seepage and Stability Cross-Section (Okanagan Survey, 2012).....	39
Figure 7-5: Modelled Critical Cross Section.....	40
Figure 7-6: Rapid Drawdown Model Conditions.....	43
Figure 7-7: Weighting Factors (Values in Parentheses) for Piping through the Embankment Mode of Failure	49
Figure 7-8: Weighting Factors (Values in Parentheses) for Piping through the Foundation Mode of Failure	50
Figure 7-9: Weighting Factors (Values in Parentheses) for Accidents and Failures as a Result of Piping from the Embankment into the Foundation	51
Figure 7-10: Estimated Annual Probability of Failure of the Elinor Lake South Dam Using Foster and Fell [2000].....	52
Figure 7-11: Existing Risk Acceptability for Elinor South Earthfill Dam Considering DFCC of 10.....	53
Figure 9-1: Overview of a Dam Safety Management System.....	59

List of Appendices

Appendix A	Site Visit Photo Report
Appendix B	Seismic Hazard Characterization
Appendix C	Seepage Analysis Results
Appendix D	Slope Stability Analysis Results
Appendix E	Dam Safety Review Assurance Statement

Executive Summary

A Dam Safety Review (DSR) of the Elinor Lake South Dam and associated works was carried out by Hatch. The review has been completed in compliance with the Engineers and Geoscientists B.C. (EGBC) Professional Practice Guidelines – Legislated Dam Safety Reviews V3.0 [EGBC, 2016], Canadian Dam Association – Dam Safety Guidelines published in 2007 (revised 2013) [CDA, 2013a], meeting the requirements of the B.C. Water Sustainability Act and the B.C. Dam Safety Regulation [Reg. 44/2016], and generally accepted engineering practice.

A dual classification system was adopted for this dam, as described in the report “Naramata Dam Breach Assessment and Inundation Mapping” (Hatch, 2021) carried out as part of this study. Under this type of system, spill capacity is solely determined based upon the potential incremental consequences of failure during a potential flood. A second classification, used for establishing the level of care for other aspects of dam safety, is determined through an evaluation of the worst case of potential incremental consequences of failure – whether caused by a Sunny Day event or failure during one of the IDF Flood events. This worst case will govern for dam classification for all aspects of dam safety except spill capacity. Elinor Lake South Dam is considered to be a High classification dam in terms of loss of life and potential damage in the event of an uncontrolled release of the impounded water for all aspects of dam safety including spill capacity. Therefore, the associated Inflow Design Flood (IDF) for this classification is 1/3 between the 1,000 year flood and PMF with a peak flow of 2.4 m³/s which can be discharged at a reservoir level of 1277.17 m.

This report represents the condition of the dam and ancillary structures at the time of the site visit on July 9, 2020. The geotechnical analysis is representative of the site conditions during construction and previous field investigations as no drilling program was included as part of this study. This constitutes the second formal DSR completed for the Elinor Lake South Dam. The first was completed in 2010 by EBA.

The discussion, conclusions and recommendations of this DSR are based on a review of selected project information including drawings, reports, manuals, photographs, instrumentation records and other miscellaneous documents as well as detailed visual site observations/assessments of all accessible components of the site and discussions with operating and surveillance staff.

This review follows a full dam breach analysis, consequence classification and inundation mapping study conducted as part of this project. The dam breach study includes an updated assessment of the hydrology/hydraulic aspects of the project, including an assessment of the IDF, and a review of the hydraulic capacity of the project. This report can be found under separate cover in Naramata Dam Breach Assessment and Inundation Mapping (2021). Results from this analysis are used to inform the studies within this report. In addition, this dam safety review includes a review of freeboard considerations to ensure capability to safely pass the specified IDF.

This review includes a review and assessment of the geotechnical and concrete components of the works, including an evaluation of the performance of the dam and foundations up to the time of the site visit, the nature, condition and suitability of the instrumentation and monitoring systems, and the process of evaluating and reporting on data.

This report recommends that the next independent DSR be done in 2030 to comply with the B.C. Dam Safety Regulation [B.C. Reg 44/2016] under the Water Sustainability Act.

As stated in the DSR assurance statement this DSR found that the “Dam is reasonably safe but the dam safety review did reveal deficiencies and non-conformances as set out in Section 12 of the attached dam safety review report”. These items are summarized along with recommended actions in the following List of New and Existing Outstanding Deficiencies and Non-Conformances. The issues identified were classified based on non-conformance, actual deficiency or potential deficiency. The actual and potential deficiencies were given an overall priority rating of the risks, defined as high, medium and low, based upon the potential of the issue leading to a critical failure of the structure. The non-conformances were assigned a ranking of high, medium or low based on how they impact dam safety. The actual or potential deficiencies and non-conformances are summarized in Table E-1.

Table E-1: Dam Safety Recommendations – Elinor Lake South Dam

Issue No.	Deficiency/Non-Conformance	Originator	Type	Status	Recommendation	Priority Rating
ES-1	Dam classification – dam is currently classified as High consequence	FLNRO, 2019 2020 DSR	N/A	Resolved	The consequence classification should be reviewed annually in accordance with the BC Dam Safety Regulation, noting changes downstream of the dam.	Low
ES-2a	Poor documentation currently exists of the dam construction and performance history, site-specific geotechnical information, embankment materials, among other details. There is one existing construction drawing showing a clay core. However, this has not been definitively confirmed. The 2010 DSR recommended a topographic survey of the dam (EBA, 2010). Lack of as-built information. Geotechnical information not available.	2010 DSR FLNRO, 2019 2020 DSR	NCi	Outstanding	If not already completed, a thorough review should be conducted for records related to design, construction and performance of the dam. In the absence of geotechnical data, detailed analyses of the dam's stability, and resilience against risks such as seepage and seismic events cannot be evaluated in detail.	Medium
ES-2b		2010 DSR	NCi	Resolved	A topographic survey of the dam was completed in 2012.	N/A
ES-2c		2020 DSR		Outstanding	A geotechnical investigation should be conducted to provide necessary input for further engineering analyses. The investigation should consist of test pits and boreholes at the dam crest to attempt to locate and characterize the material zones of the dam, if present. Laboratory and in-situ testing should be conducted to determine the material properties. Piezometers should be installed during investigation.	High
ES-2d	Lack of instrumentation.	2020 DSR	NCi,s	Outstanding	Piezometer(s) should be installed with the borehole drilling to enable continued monitoring of the pore water pressure conditions within the dam.	High
ES-3	There is currently no ability to measure quantity of seepage in areas where seepage has been observed historically.	2010 DSR 2020 DSR	NCi,s	Outstanding	Install or reinstate the weir at the outlet of the drain to allow for quantitative measurement of seepage flows.	Medium
ES-4	Evidence of seepage was observed at the downstream toe. However, heavy vegetation limited access to the area where seepage was observed.	2010 DSR FLNRO, 2019 2020 DSR	NCs	Outstanding	Extend limits of vegetation clearing downstream of the dam to allow for inspection of the toe and regular seepage observations.	Medium
ES-5	A detailed geotechnical assessment could not be completed due to the absence of construction documentation and site-specific geotechnical data. The dam is potentially susceptible to failure modes including slope instability, piping, and liquefaction.	2010 DSR 2020 DSR	NCi	Outstanding	Geotechnical assessments should be undertaken upon completion of the recommended geotechnical investigation. These should evaluate risks of common failure modes including seismic and normal slope stability, piping, and liquefaction. It is expected that the results of these assessments may lead to a recommendation for construction of a toe berm or similar improvements to limit seepage and increase the stability of the dam at the downstream toe. In addition, internal stability assessment of dam core and filter compatibility assessment should be conducted.	High
ES-6	The risk of piping failure was found to be in the unacceptable risk zone as outlined by the CDA Guidelines (EBA, 2010)	2010 DSR	NCi, An	Outstanding	The risk level remains similar to the previous assessment. The recommendations above to complete a geotechnical investigation and improve seepage monitoring and instrumentation can contribute to reducing the risk of piping failure.	Medium
ES-7	Topographic survey data from 2012 shows the dam crest elevation is lower than the design elevation of El. 1278 m (EBA, 2013). However, freeboard requirements are met according to CDA.	2010 DSR FLNRO, 2019 2020 DSR	NCm	Outstanding	Place material to re-grade the crest to the design/typical elevation to provide additional freeboard, in line with FLNRO Plan Submission Requirements for the Construction and Rehabilitation of Small Dams.	Medium
ES-8	Security/access issues leading to damage on dam crest and face from ATV traffic. Recent inspections also note damage by cattle and vehicles.	2010 DSR FLNRO, 2019 Risk Survey, 2020 DSR	NCp	Outstanding	Review security and access protocols and implement appropriate restrictions including those recommended in the 2019 Risk Control Study (Precise Services, 2019) to prevent damage or vandalism.	High
ES-9	No Operations, Maintenance and Surveillance (OMS) manual was prepared for the dam as of the previous Dam Safety Review	2010 DSR	-	Resolved	An OMS manual has been published since the previous review (RDOS, 2017). The contents of the OMS were reviewed and revised as part of the 2020 review.	N/A
ES-10	Dam Safety Review schedule	2020 DSR		New	In accordance with the High consequence classification, the next Dam Safety Review should be conducted in 2030, and every 10 years thereafter.	N/A
ES-11	Dam Emergency Plan – the Emergency Preparedness Plan (EPP) should be updated to comply with the updated requirements for a Dam Emergency Plan (DEP) in the Dam Safety Regulation	FLNRO, 2019	-	Resolved	The Dam Emergency Plan has been updated as part of this review.	N/A

Issue No.	Deficiency/Non-Conformance	Originator	Type	Status	Recommendation	Priority Rating
ES-12	Lack of sufficient instrumentation and data assessment for performance monitoring	2020 DSR	Nci,s	New	The instrumentation monitoring shall include continuous records, plotting, and interpretation of seepage flow quantities against reservoir elevation. The piezometer information should be closely monitored once available.	Medium
ES-13	Currently no riprap or erosion protection layer on the dam crest or upstream slope.	2020 DSR	NCm	New	Provide appropriately sized armour protection along the upstream face of the dam from the crest to 1 m below the low water level.	Low
ES-14	LLO structure is unprotected from vandalism and accidental damage from ATVs or other traffic at dam crest.	2020 DSR	NCm	New	Provide protection to the screw stem by adding bollards or a steel cover to prevent damage from ATV traffic.	Low
All-1	OMS could be improved by including supporting confirmation that highlighted maintenance activities are being completed.	2020 DSR	NCs	New	Regular verification of the completion of maintenance items recorded in the weekly site surveillance form would further support that maintenance items are being completed.	Low
All-2	OMS does not have a table with positions and associated names describing roles and responsibilities.	2020 DSR	NCo	New	Update table in OMS to include positions and associated names describing roles and responsibilities.	Medium
All-3	Routine Dam Inspection Report format does not contain all aspect of BC Dam Safety Office's Site Surveillance Form for weekly inspections.	2020 DSR	NCp	New	Routine Dam Inspection Report format should be improved to more closely follow the BC Dam Safety Site Surveillance Form for weekly inspections.	Low
All-4	No formal Dam Safety Policy is in place for their dam safety program.	2020 DSR	NCp	New	The RDOS appears to be meeting the intent of a dam safety management system and should continue to improve and develop their system and adopt a formal policy statement on Dam Safety for their program to satisfy the CDA Dam Safety Guidelines. This will demonstrate a commitment to the regulation and provide a reason to perform necessary works.	Medium
All-5	OMS could be improved by including more information to assist Dam Safety inspectors in detecting and responding to an emergency situation.	2020 DSR	NCp	New	In the OMS, inflow forecasting should include alarm limits on what scenario of Snow Survey combined with reservoir levels would create a need for action. Actions to be taken should be described. Any recommended drawdown in anticipation of large spring runoff events should also be documented.	Medium
All-6	Emergency notification systems to alert the public should be expanded to include a text message template to facilitate public notification in the event of an emergency.	2020 DSR	NCp	New	It is recommended that the RDOS emergency call alert system, CivicReady be setup to allow for public signup in order to receive external text message notifications during an emergency.	Medium
All-7	No available documentation provided to show if regular dam safety training is provided to the inspector(s).	2010 DSR, 2020 DSR	NCs	Outstanding	RDOS staff responsible for the DEP should regularly attend BC Dam Safety Dam Management seminars on dam safety and inspections (understood to be provided annually in most areas of BC, including Penticton). Records of attendance at these inspection workshops should be documented along with information on any additional training completed. This could include review of material provided on BC Dam Safety website.	Medium
All-8	No available documentation to show that exercises are carried out regularly to test the emergency procedures.	2020 DSR	NCp	New	Provide documented training to staff in emergency procedures, and carry out and document regular exercises to test the emergency procedures. Follow additional recommendations in proposed new Dam Emergency Plan (DEP) procedure.	Medium

Refer to Table 12-1 for legend and definitions of the type of deficiencies and non-conformances.

1. Introduction

1.1 DSR Report Purpose and Scope

This report has been prepared by Hatch Ltd. (Hatch) for the Regional District of Okanagan-Similkameen (RDOS) to document the Dam Safety Review (DSR) that was conducted for the Elinor Lake South Dam. The review has been completed in compliance with the Engineers and Geoscientists B.C. (EGBC) Professional Practice Guidelines – Legislated Dam Safety Reviews V3.0 [EGBC, 2016], Canadian Dam Association – Dam Safety Guidelines published in 2007 (revised 2013) [CDA, 2013a], and meeting the requirements of the B.C. Water Sustainability Act and the B.C. Dam Safety Regulation [Reg. 44/2016]. The scope of services provided are outlined in RDOS contract RDOS-20-PW-04 between Hatch Ltd. and the Client dated May 8, 2020 and in accordance with Hatch Proposal No. 031390 dated March 23, 2020.

1.2 Previous Dam Safety Reviews

The most recent Dam Safety Review for the Elinor South Dam was completed in 2010 by EBA Engineering under the previous version of the B.C. Dam safety regulation. According to the B.C. Dam Safety Regulation (B.C. Reg 44/2016) under the Water Sustainability Act, a new Dam Safety Review is required in 2020.

1.3 Objective

The objective of this Dam Safety Review is to determine if the dam facilities meet the recommendations in the Engineers and Geoscientists B.C. (EGBC) Professional Practice Guidelines – Legislated Dam Safety Reviews V3.0 [EGBC, 2016], Canadian Dam Association – Dam Safety Guidelines [CDA, 2013a], and the requirements of the B.C. Water Sustainability Act and the B.C. Dam Safety Regulation [Reg. 44/2016], and to present the findings as either confirmation of the dam's safety, or identification of deficiencies, non-conformances and issues for further investigation. The scope of the complete Naramata Dams study includes a dam breach and inundation study including dam failure consequence classification, Inflow Design Flood (IDF) selection and inundation zone mapping. Results from this work are used to inform this DSR.

The major conclusions and recommendations of this DSR for the Elinor Lake South Dam components have been summarized at the end of this report. The recommendations have been ranked using the prioritization system outlined in Section 13.

2. Description of Development

2.1 General

There are four Naramata area dams located from elevations 900 m to over 1250 m above the main populated regions along Okanagan Lake in British Columbia. These dams include:

- Big Meadow Lake Dam
- Elinor Lake North (Saddle) Dam
- Elinor Lake South Dam
- Naramata Lake Dam.

The locations of these dams are shown in Figure 2-1.




Figure 2-1: Naramata Dams Location Map

The Elinor Lake North Dam and Elinor Lake South Dam is a part of this four-dam system which forms three interconnected reservoirs that provided a historical upland source of potable water to the Township of Naramata. The dams were constructed during the first half of the twentieth century by the Naramata Irrigation District (NID), which has been subsequently incorporated into the Regional District of Okanagan-Similkameen (RDOS). These dams are no longer required for the potable water due to the construction of Naramata UV Water treatment Facility in 2006, and the RDOS continues utilizing these facilities for maintaining essential creek flows, emergency backup supply of water and supplying irrigation water to agricultural lands.

2.2 Site Description

The Elinor Lake North and South Dams are situated in a north to south trending valley situated approximately 9.2 km and 8.4 km respectively to the northeast of Naramata Township.

The Elinor Lake South Dam is approximately 83.8 m long and 5.8 m high at its maximum height with a crest elevation ranging from 1277.44 m to 1277.94 m. Flows from the Elinor Lake Reservoir discharge via a low level conduit through Elinor Lake South Dam into Robinson Creek which in turn discharges into the Naramata Lake Dam Reservoir.

Vehicle access to the dams is provided via Elinor Lake Forestry Service Road, which extends off Chute Lake Road to the north which in turn extends off North Naramata Road to the west.

Figure 2-2 illustrates the current configuration and nomenclature used for the remainder of this report to identify the various parts of the structures.



Figure 2-2: Elinor Lake South Dam Major Component Layout

2.2.1 Instrumentation

Currently, no instrumentation exists at the Elinor Lake South Dam. Sandbags, plastic liner, and PVC pipes are provided at the right side of the LLO outlet pipe structure which enable the measurement of seepage quantity. On the left side, the drainage pipes exist with no sandbags.

2.2.2 Dam and Reservoir Summary Information

The key physical dimensions of the Elinor South Dam are in Table 2-1.

Table 2-1: Key Dimensions of Elinor Lake South Dam

Structure	Details
Type of Dam	Embankment Dam (Zoned Earthfill with central clay core)
Maximum Height	5.8 m
Crest Length	83.8 m
Crest Width	3.5 m
Crest Elevation	1277.44 m minimum to 1277.94 m maximum
Upstream Slope	2.5H:1V
Downstream Slope	3.5H:1V
Retained Water (at spillway crest)*	271,000 m ³
Low Level Outlet	Concrete with metal gate, steel conduit, concrete outlet Invert elevation 1272.4 m 457 mm (18" diameter)
Spillway	Grassed channel leading to concrete sill with grassed sides and abandoned stoplog slot, 3 m wide Spillway crest elevation 1276.55 m
Dam Failure Consequence Classification	High
Full Supply Level (FSL)	1276.55 m
IDF Level	1277.08 m
IDF	2.4 m ³ /s

2.3 History of Dam and Reservoir

Limited information is available with respect to the design and construction of the Elinor Lake South Dam. Based on the review of the existing drawings of the South Dam, it was originally constructed in 1946 and comprises a granular earthfill embankment with central clay core. A review of the oldest available aerial photography from 1938 indicates that two interconnected lakes existed at the location of the reservoir prior to construction of the dams.

The existing drawings of the South Dam indicate that it has a 2.5H:1V upstream slope and 3.5H:1V downstream slope. An 18-inch (457.2 mm) diameter steel discharge conduit was grouted into the original concrete culvert and extended at the downstream slope of the South Dam in 1959, however it is unknown if there was a modification of the downstream slope at

this time. A drawing dated 1966 (No. 1316 by BC Department of Lands, Forest, and Water Resources – Water Right Branch) shows the details of the culvert gate repairs. As the drawing shows, the intake structure was modified by decommissioning the intake tower and constructing a sliding sluice gate operated by a gate rod.

In the inspection of the South Dam in 1991, significant seepage was noted along the toe of the embankment, and installation of a 1.0 m deep granular toe drain incorporating a 0.3 m diameter perforated pipe was recommended; however, it is unknown if these works were undertaken.

3. Dam Safety Review Methodology

This DSR is based on a review of available documentation, discussions with the RDOS staff and a site inspection at the Elinor South Dam. The scope of the review includes the dam's physical condition, operation, maintenance, surveillance, emergency planning and response, dam performance and dam safety management process, as these pertain to overall dam safety management of the Elinor South Dam.

The project commenced with document review that included the project performance expectations, including flood and earthquake criteria, based on the Canadian Dam Association – Dam Safety Guidelines [CDA, 2013a], and the B.C. Water Sustainability Act and the B.C. Dam Safety Regulation (Reg. 44/2016). Prior dam safety reports and other reports pertaining to the safety of Elinor South Dam were made available to Hatch. A full listing of documents reviewed is provided in Section 4.

The Hatch team performed a site inspection as discussed in Section 5.

The DSR focuses on the history of the dam with attention to issues and work that had been performed since the last DSR [EBA, 2010] and encompassed the BC Dam Safety Regulation [B.C. Reg. 44/2016] and the CDA Guidelines [CDA, 2013a]. Where the aspects of the Dam Safety Management Program were found not to conform, the issue was identified as a deficiency or as a non-conformance and a recommendation for follow-up action was made. The identified deficiencies were categorized as being: physical deficiencies (inadequate dam performance condition); or deficiencies of the physical infrastructure of the dam (such as the system for the collection of data and observations necessary to verify the physical performance of the dam); or procedural non-conformances. The priority rating of the various risks were defined as either high, medium and low, based upon the potential of the issue leading to critical failure of the structure in order to provide the RDOS recommended priorities to resolve these deficiencies.

Based on an understanding of hazards and associated failure modes, a “Hazards and Failure Modes Matrix” was created (see Section 7.1) that lists potential hazards and failure scenarios for the Elinor South Dam.

The findings of the DSR were documented in this DSR Report.

4. Data Collection and Review

4.1 Existing Information

RDOS provided available information on the dam to Hatch for this DSR. Historical data was provided as electronically scanned documents and was contained in various folders.

Table 4-1 summarizes each document that was reviewed.

Table 4-1: Existing Information Summary

File Name	Data	Description
Drawings		
Chute Lake Diversion – Existing Structure	October 1993	Spillway drawings
Naramata Lake Historical Drawings	1967 – 1978	Design drawings, area maps, topography, storage capacity, cross-section drawings, borrow areas (Drawing No.226-02-1 to 226-02-8 and Kelowna No. 1203)
Naramata Lake Dam – Remedial Filter Blanket	1969	Details of drains downstream of dam (Drawing No. 226-02-100)
Naramata Lake Dam – Piezometer Location Plan	Unknown	Shows the location of test well
Eleanor Lake Dam – Details of Culvert Gate Repairs	December 1966	Culvert gate repair plans for Elinor Lake Dam (Drawing No. 1316)
Eleanor & Naramata Lakes – Plan of Storage	17 April 1964	Storage plans for Elinor and Naramata Lakes (Drawing No. Kelowna-1203)
Improvements – South and North Intakes	6 December 1979	Improvements to South and North intakes of Elinor Lake Dam
Big Meadow Reservoir Plan of Storage	8 April 1963	Storage plans for Big Meadow Dam (Drawing No. Kelowna 1114)
Big Meadow Lake Storage Dam	November 1952	Spillway cross-sections (in sketch format)
Big Meadow Lake Reservoir – Plan of Reservoir	September 1979	Plan of Reservoir (Drawing No. 4567-5)
Big Meadow Dam – Details of Repairs to Culvert Gate & Outlet	19 September 1966	Repair plans to culvert gate and outlet (Drawing No. 1315)
Big Meadow Lake Reservoir – Plan of Reservoir	March 1982	Storage tables, rating curves for Big Meadow Reservoir
Big Meadow Dam – Grill at Gates	August 31, 1920	
Topographical Survey and Mapping		
Big Meadow Dam Site Topography	17 July 2012	Topographical survey from Okanagan Survey & Design
Elinor Lake – North Dam Site Topography	24 July 2012	Topographical survey from Okanagan Survey & Design
Elinor Lake – South Dam Site Topography	24 July 2012	Topographical survey from Okanagan Survey & Design

File Name	Data	Description
Naramata Lake Dam – Site Topography	24 July 2012	Topographical survey from Okanagan Survey & Design
Naramata Creek Watershed Area – Map 5: Groundwater Sensitivity Zones	21 December 1998	Groundwater sensitivity zones, recharge and discharge zones, flow and surface hydrology sensitivity zones for the Naramata watershed
Photos		
Big Meadow Lake Dam Site Photos	2010	
Elinor Lake Dams Site Photos	2010	
Naramata Lake Dam Site Photos	2010	
Naramata Water System North and South Creek Intake Photos	12 March 2020	
Inspection Reports (by RDOS staff)		
Naramata Dams Status Reports FLNRO	2002 to 2019	Dam Status report forms
Correspondence		
Naramata Dams FLNRO Dam Audit Program	Emails to 21 November 2019	Email correspondence on Audits between 2004-2019
Big Meadow Dam	2 November 2004.	Correspondence from Golder regarding insitu density testing along a repaired section of the south east abutment of the Big Meadow Dam.
Reports		
Risk Control Survey	2019	Review of RDOS facilities to identify exposures to liability and to assist staff in managing these exposures.
Big Meadow Reservoir and Dam Operation, Maintenance and Surveillance Plan Emergency Preparedness Plan	May 2017	OMS and EPP Plan from RDOS
Elinor Lake Reservoir and Dams Operation, Maintenance and Surveillance Plan Emergency Preparedness Plan	May 2017	OMS and EPP Plan from RDOS
Naramata Lake Reservoir and Dams Operation, Maintenance and Surveillance Plan Emergency Preparedness Plan	May 2017	OMS and EPP Plan from RDOS
Naramata Uplands Waterworks (Diversion, Divide, Flume, Highline & Intakes - Maintenance and Surveillance Plan	April 2013	Maintenance and Surveillance Plan from RDOS
Big Meadow Lake Dam Geotechnical Assessment	11 January 2013	EBA Consultants 2013 Geotechnical Assessment Report
Topographical Survey of Naramata Dams	10 January 2013	EBA Consultants memo accompanying topographical survey.-EBA File: 13103018

File Name	Data	Description
Dam Safety Review – Big Meadow Lake Dam	17 December 2010	EBA Consultants 2010 Dam Safety Review – No. K13101459.001
Dam Safety Review – Naramata Lake Dam	17 December 2010	EBA Consultants 2010 Dam Safety Review– No. K13101459.001
Dam Safety Review Summary Report – Naramata Dams	21 December 2010	EBA Consultants 2010 Dam Safety Review– No. K13101459.001
Dam Safety Reviews for Elinor Lake North (Saddle) Dam and Elinor Lake South Dam	17 December 2010	EBA Consultants 2010 Dam Safety Review– No. K13101459.001
Hydrotechnical Assessment of the Naramata Dams	20 December 2010	EBA Consultants 2010 Hydrotechnical Assessment Report
Naramata Fan Study (with Robinson and Chute Creeks)	December 1994	BC MoE Naramata Fan Study
Naramata Lake Operation and Maintenance Manual	April 1993	Naramata Irrigation District Operation and Maintenance Manual.
Big Meadow Reservoir – Storage Capacity Table	26 April 1979	Storage capacity table using survey data from Kelowna Regional Office Water Rights Branch
Eleanor Lake Reservoir – Storage Capacity Table	17 August 1979	Storage capacity table using survey data from Kelowna Regional Office Water Rights Branch
Naramata Lake Reservoir – Storage Capacity Table	29 June 1979	Storage capacity table using survey data from Kelowna Regional Office Water Rights Branch

4.2 Data Gaps

RDOS provided information available for Elinor Lake South Dam including some of the engineering and dam safety studies that have been completed for the Elinor South Dam during the life of the structure. This documentation included previous dam analyses conducted by external consultants as well as reports from inspections completed by RDOS personnel and RDOS Operations, Maintenance and Surveillance (OMS) information.

The project consists of structures that were constructed from 1946 to 1959 and have largely gone unchanged throughout the intervening years. A complete record of information on the design and construction of the dam was not available. For the analysis in this review, it has been assumed that the general information contained in the data files received from RDOS reflects the current condition of the structures.

The data gaps that were identified during this review include:

- No construction specifications,
- A lack of geotechnical information including:
 - ◆ Internal zoning geometry
 - ◆ Material gradation and in-situ compaction

- ◆ Gradation and density of the foundation material and depth to bedrock
- ◆ Shear strength information on the impervious fill, shell and foundation materials
- ◆ Piezometric elevations in the dam and foundation.

Recommendations to fill some of these gaps are presented in the conclusions and recommendations sections of the report but none of these prevented the completion of the DSR by making appropriate assumptions when needed, based on existing information.

5. Site Inspection and Staff Interviews

Hatch conducted a one (1) day site inspection to Elinor Lake South Dam for this Dam Safety Review (DSR). The site inspection was conducted on July 9, 2020 and attended by Hatch's Structural Engineer/Project Manager (Amit Pashan, P.Eng.), Geotechnical Engineer (Parham Ashayer, P.Eng.) and Hydrotechnical Engineer (Shayla Murphy, P.Eng.). The following personnel from RDOS also attended the site inspection: Shane Fenske (RDOS – Engineering Technologist and Naramata Dams Dam Safety Review Project Manager), and Jon Hillman (RDOS Dam Inspector).

The purpose of this site inspection was for the Hatch DSR Team to:

- Gain familiarity with the site
- Inspect the various structures and equipment and document any observed deficiencies
- Discuss aspects of RDOS's dam safety inspection and monitoring program
- Discuss operational and dam safety aspects of the Elinor Lake Dam site and RDOS's operations and maintenance staff.

Photos referred to in the following sections can be found in Appendix A.

5.1 General

A general walkover and inspection of the Dam structures was performed. The Dam is within a remote area, yet clear indicators of public access were present. The reservoir rim was found to be generally next to natural higher ground with dense trees surrounding the entire lake. A review of the reservoir rim at the dam crest was completed and was found to be well maintained in this area, and in proper condition with no sign of failure or distress. No significant dead wood was observed in the lake which would supply debris that could potentially impact the structure or spillway. It was noted that peat islands can be found in this lake, but that campers and hunters typically remove them for their own use. In general peat islands can be a concern for plugging the spillway, however the debris boom should be adequate to keep the peat out of the spillway, these should be monitored and removed from the debris boom as needed. Minor vegetation growth was observed above the water level (which was slightly above the spillway crest elevation during the site visit) on the upstream slopes of the dam (see Photos A1 to A5 in Appendix A). Historical photos from the previous DSR (EBA, 2010) show sand and gravel on the upstream slope of the dam. No riprap was found on the upstream face of the dam, notably, no sign of erosion or distress could be found on the upstream face due to wave and surge actions.

5.1.1 **Freeboard**

The crest of the dam varies significantly in elevation along its entire length, from 1277.44 m to 1277.94 m.

Flood routing and freeboard analyses were completed, demonstrating that the existing freeboard will provide adequate protection due to wind generated waves. Given that there is currently no riprap or erosion protection layer on the upstream slope, it is recommended that RDOS inspect the dam after large wind storms to confirm if any damage has occurred and repair as necessary. This requirement has been added to the OMS. Provision of appropriately sized armor protection along the upstream face of the dam from the crest to 1 m below the low water level should be considered and is described in further detail in Section 7.2.6.

Although there is a definite ATV presence in the area, the dam crest itself did not appear to be significantly affected by this traffic. To note, it is the only dam of the four Naramata Dams with a riprap layer on the dam crest (although none is present on the slopes).

5.2 **Elinor Lake South Earthfill Dam**

The South earthfill dam consists of granular shells on the upstream and downstream sides with an impervious central core which acts as the water barrier. There is no riprap on the upstream face of the dam. Minor vegetation growth including grass and short bushes was observed on the upstream slope above the reservoir water level. The reservoir level was high during the Hatch inspection, with water flowing over the spillway.

A review of dam photos during the EBA (2010) inspection shows the presence of granular materials on the upstream face of the dam. The downstream slope of the South Dam is also comprised of granular materials covered by grasses and short bushes (see Photo A5). The downstream slope was found to be relatively shallow, and the existing drawing shows a typical slope of 3.5H:1V. The existing drawing shows the upstream slope at 2.5H:1V. Vegetation (grass) growth on the slopes do not appear to be an issue and are in fact considered to be favorable against erosion. The vegetation on the upstream slope of the South Dam was found to be scrubby which requires continuous effort to maintain. No erosion of the slopes was observed.

Seepage flow was observed on the right side of the LLO exit structure (see Photos A6 and A7). A close inspection of the seepage indicated that it was generally clear with no fine content. RDOS has created a seepage collection zone on the right side of the embankment dam with a plastic liner and sandbags. This creates an opportunity to measure and monitor the seepage quantity. Wet condition was also found on the left downstream side of the intake structure; however, no visible seepage flow could be detected. It is suspected that the seepage flow visible on the sides of the intake structure is collected by a granular toe drain with a perforated collection pipe buried at the toe of the South Dam, but there is no drawing or report available to confirm whether or not it exists or the details of construction if it does exist. No sign of distress, instability or deformation was found in the downstream slope.

Ponding was observed at the toe of the dam on the left side of the LLO structure (see Photos A8 and A9). A seepage point was observed and surveyed by Okanagan Survey (2012) approximately 20 m east of the LLO structure which could be a source of the seepage to the pond. With the existing level of information, the source of seepage cannot be confirmed. The water may seep through the dam core, the contact of the culvert and dam core, or foundation materials. Seepage may take place through abutment(s) as well.

The downstream toe of the dam was covered in dense vegetation, trees, and dead trees which resulted in an inaccessible condition for inspection (see Photos A8 and A9). It is recommended to extend the cleared area of trees and shrubs to allow for a more detailed and structured inspection of the dam toe.

Hatch could not locate a seepage monitoring weir along the LLO channel. It is recommended to install a weir along the channel in order to measure seepage (see Issue No.ES-3 in Table 13-1).

The crest of the Elinor South Dam is a publicly accessible unpaved road in fair condition (see Photos A1 and A2). No sign of distress, cracks, or significant erosion were observed. The crest of the dam appeared to be relatively variable in elevation as indicated in the 2012 topographical survey. The dam crest is at its lowest elevation at an El. 1277.44 m at areas close to right abutment and the crest elevation gradually increases to an El. 1277.94 m close to left abutment.

No issues were noticed on the right abutment of the dam aside from being slightly lower than the dam crest. Trees were found growing on the upstream and downstream slopes, immediately next to the left abutment.

On the left abutment, the embankments tie into the spillway channel. The spillway at the dam intersection is lined with riprap. In areas beyond the spillway channel, the ground rises to high elevation.

5.3 Spillway

The spillway at the Elinor South Dam was observed by Hatch during the site inspection (see Photos A11 to A14) and appeared to be in fair condition. The Elinor Spillway is essentially an excavated channel on the left abutment of the Elinor South Dam and lined with masonry rocks with no mortar. Minor vegetation growth was observed almost along entire length of the spillway channel. Water was flowing over the spillway at the time of inspection which hindered a review of the entire length of the spillway and detailed inspection of the channel and side walls. It is recommended to conduct a detailed condition assessment of the spillway lining during a low water level. The vegetation on the channel should be controlled so as not to impede the spillway discharge capacity.

The spillway concrete weir is located immediately in line with the dam crest. The spillway crest appeared to have provision to insert stoplogs which are no longer used. The concrete of the spillway crest was in fair condition with no signs of major deterioration, spalling or exposure of rebar. Most of the spillway crest is keyed in the riprap on upstream and

downstream of the crest. Therefore, only the top surface of the crest was visible during the site visit. Due to presence of riprap support, there were no signs of undermining of spillway crest structure. It is recommended that the vegetation growth in the spillway and on the crest be cleaned to maintain the flow through the spillway and to prevent any deterioration of concrete on the spillway crest.

There is a debris boom upstream at the inlet structure to prevent debris from clogging the weir. This boom should be adequate for this purpose provided debris is removed on a regular basis and not allowed to build up excessively.

5.4 Low Level Outlet Intake Structure

The intake structure comprises of an 18-inch diameter 12-gauge steel pipe encased with concrete, which runs along the base of the embankment dam. An 18-inch Armco heavy duty slide gate is installed at the upstream/intake end of the concrete encased pipe culvert. The slide gate is connected with a 1-1/2" diameter gate rod and is operated via a rotating wheel assembly at the dam deck level. Most part of the intake structure was under water during the site visit and therefore could not be visually inspected. Only the section of the wheel assembly and its concrete anchor support at the dam crest, and some portion of the intake gate operating rod were visible above water (see Photo A16). The concrete at the wheel block support assembly appeared to be in good condition. Some signs of corrosion were observed on the gate operating rod and the wheel assembly however, no evidence of damage was noted. The operating wheel was not attached to the assembly at the time of visit and it is kept offsite by RDOS staff and used while operating the intake gate. According to site staff, the intake gates operate successfully, and no concerns were indicated related to the operation of these gates. The operation of the intake gate was not verified during the site visit.

The inspection of the trash rack grill at the inlet and the concrete support structure at the inlet of the culvert is recommended to be performed during the time of low lake levels, for any signs of distress, settlement or damage. The observations from the inspections should be documented for future reference, and any concerns if found, should be addressed.

A significant ATV traffic activity appears to be present in general at the dam sites and was more evident at Elinor North Saddle Dam location with ATV tracks on downstream slope of dam. The dam area is open for recreational use and there is no fence around the dam crest. Since the operating wheel assembly is located at the dam crest, a possible concern could be potential damage to this operating structure due to accidental ATV activities or vandalism. In the event the structure is vandalized, the damage may remain unnoticed for several days as the dam site is not manned. It may be concerning if the gate operating assembly is found to be damaged/inoperable in an event a gate operation is needed in emergency such as after a major seismic event when RDOS may need to lower the reservoir water level. Concrete barrier blocks or fencing of the area should be considered around the wheel assembly and the gate rod as a precautionary measure. These types of solutions can prevent the potential risk of damage to the operating structure and can be implemented at a relatively low cost.

5.5 Low Level Outlet Structure

The outlet is a small concrete structure at the downstream toe of the dam, as shown in the existing drawing No. 1316. This structure supports the downstream end of an 18-inch diameter culvert pipe.

The concrete of the outlet structure was found to be in good condition. There was no evidence of any damage, spalling of concrete or exposure of rebar (see Photos A6 and A7). The walls of the outlet structure were visually verified, and no signs of tilting or deformation were noted.

6. Consequences of Dam Failure and Dam Classification

A full dam breach analysis and consequence classification and inundation mapping study was conducted as part of this project. The results of this analysis can be found under separate cover in Naramata Dam Breach Assessment and Inundation Mapping (2021). The following subsections summarize the results of this study.

6.1 Background Information

Dam classifications are used for the purpose of general dam safety management oversight, as well as for inspection, maintenance, and surveillance programs. Dam classifications provide guidance in the selection of specific design criteria such as, in the case of this study, IDF, freeboard, and stability criteria. B.C. Dam Safety Regulations present a classification scheme, presented in Table 6-1 and Table 6-2, which are used to provide guidance on the standard of care expected of dam owners. Estimates of potential consequences of dam failure are categorized to distinguish dams where the risk is much higher than others. The dam class is determined by the highest potential consequence, whether loss of life, environmental, cultural, or economic losses.

Table 6-1: Consequence Classification Guide (B.C. Dam Safety Regulation, Water Sustainability Act Dam Safety Regulation 40/2016)

Dam Failure Consequence Classification	Population at Risk	Consequences of Failure		
		Loss of Life	Environment and Cultural Values	Infrastructure and Economics
Low	None ¹	No possibility of loss of life other than through unforeseeable misadventure.	Minimal short-term loss or deterioration and no long-term loss or deterioration of: a) Fisheries habitat or wildlife habitat b) Rare or endangered species c) Unique landscapes, or d) Sites having significant cultural value.	Minimal economic losses mostly limited to the dam owner's property, with virtually no pre-existing potential for development within the dam inundation zone.
Significant	Temporary Only ²	Low potential for multiple loss of life.	No significant loss or deterioration of: a) Important fisheries habitat or important wildlife habitat b) Rare or endangered species c) Unique landscapes, or d) Sites having significant cultural value, and restoration or compensation in kind is highly possible.	Low economic losses affecting limited infrastructure and residential buildings, public transportation or services or commercial facilities, or some destruction of or damage to locations used occasionally and irregular for temporary purpose.
High	Permanent ³	10 or fewer.	Significant loss or deterioration of: a) Important fisheries habitat or important wildlife habitat b) Rare or endangered species c) Unique landscapes or d) Sites having significant cultural value, and restoration or compensation in kind is highly possible.	High economic losses affecting infrastructure, public transportation or services or commercial facilities, or some destruction of or some severe damage to scattered residential buildings.
Very high	Permanent ³	100 or fewer.	Significant loss or deterioration of: a) Critical fisheries habitat or critical wildlife habitat b) Rare or endangered species c) Unique landscapes, or d) Sites having significant cultural value, and restoration or compensation in kind is possible but impractical	Very high economic losses affecting important infrastructure, public transportation or services or commercial facilities, or some destruction of some severe damage to residential areas.
Extreme	Permanent ³	more than 100.	Major loss or deterioration of: a) Critical fisheries habitat or critical wildlife habitat b) Rare or endangered species c) Unique landscapes, or d) Sites having significant cultural value, and restoration or compensation in kind is impossible.	Extremely high economic losses affecting critical infrastructure, public transportation or services or commercial facilities, or some destruction of or some severe damage to residential areas.

¹ There is no identifiable population at risk.

² People are only occasionally and irregularly in the dam-breach inundation zone, for example stopping temporarily, passing through on transportation routes or participating in recreational activities.

³ The population at risk is ordinarily or regularly located in the dam breach inundation zone, whether to live, work or recreate.

Table 6-2: B.C. Dam Safety Regulation Downstream Dam Failure Consequence Classification (DFCC) Guide

DFCC	Inflow Design Flood
Extreme	PMF
Very High	2/3 between AEP 1/1,000 and PMF
High	1/3 between AEP 1/1,000 and PMF
Significant	AEP between 1/100 and 1/1,000
Low	AEP 1/100

6.2 Previous Work by Others

The Elinor Lake South Dam is currently classified as High. The report, “Hydrotechnical Assessment of the Naramata Dams” (2010) was produced in tandem with the previous most recent Dam Safety Reviews by EBA Engineering Consultants, which classified Elinor South Dam as High.

However, a complete incremental damage and loss of life assessment and full dam breach and inundation study had not previously been performed for this dam. Previous classification assessments were conducted prior to the publication of the current CDA Dam Safety Guidelines [CDA, 2013a).

6.3 Recommended Classification

To determine the appropriate consequence classification, it was necessary to first assess the effect of a breach on the downstream area and inhabitants during “fair weather” and flood scenarios. This was carried out by Hatch as part of this study and is documented in a separate report entitled Naramata Dam Breach Assessment and Inundation Mapping (2020).

The CDA Technical Bulletin on Inundation, Consequences and Classification for Dam Safety (2007) and the BC Dam Safety Program “Downstream Consequence of Failure Classification Interpretation Guideline” provides guidance on the application of consequence assessments to aspects of dam design and dam safety:

- Incremental consequences of dam failure in flood conditions define the minimum requirements for the IDF.
- Consequences of dam failure in fair weather conditions define the minimum requirements for seismic loading.
- The higher of the two dictates the overall level of care in management oversight, inspection, maintenance, and safety assessment.

Elinor South Dam has been classified according to the current B.C. Water Sustainability Act Dam Safety Regulation [B.C. Reg 44/2016] dam classification system. The consequence assessment found that the classification for flood conditions was the same as for fair weather conditions. Results confirm that the overall classification for Elinor South Dam is “High”, and

that the incremental damages due to a potential IDF are in line with a “High” classification as well (i.e. this defines the minimum requirements for IDF).

The classifications provided in this report apply to the existing dam in its present configuration. Alterations to the dam could change parameters such as the volume and/or height of impounded water, the flood routing capacity of the dam, or potential breach characteristics. This in turn could impact the nature and magnitude of consequences of failure and therefore the appropriate classification and design criteria. In the event of substantial alterations, flood routing calculations need to be updated and the potential consequences of failure reassessed by means of additional or revised dam breach analyses as needed.

7. Dam Safety Analyses

One of the basic requirements of a DSR is the engineering analysis and assessment of the structure. The CDA Guidelines state “Safety analysis of the dam system should include the internal and external hazards, failure modes and effects, operating reliability, dam response, and emergency scenarios.”

Also as stated in the CDA Bulletin on Analysis and Assessment “The purpose of dam safety analysis is to determine the capability of the dam and systems to retain the stored volume and to pass flows around and through the dam in a controlled manner.”

The following subsections detail the dam safety analysis that were performed as part of this DSR.

7.1 Failure Modes and Effects Analysis

A hazard and failure mode matrix was developed for the Elinor South Dam and is presented in Table 7-1. In this type of assessment, the interactions between hazards and failure modes are related using a matrix representation. The hazards and failure modes matrix (H&FMM) provides a simple means of summarising the considerations that, in principle must be embodied in every dam safety program. It provides a framework in which the various hazards and failure modes can interact and act in combination to lead to dam failure. Although the site consists of the dam and a spillway, the failure modes listed are generally applicable to the site as a whole.

In a risk based evaluation of failure modes, risk can be described as the combination likelihood of a failure mode occurring (probability of the failure mode) with the consequence of what would happen should a failure mode occur (loss of containment of the reservoir). This is calculated in a quantitative assessment as $Risk = Likelihood \times Consequences$. The intent of a Dam Safety Review is to ensure that the dam is constructed and operated in a manner to ensure the risk to the public is within the “broadly acceptable” range or where this is not possible, to reduce the risks to as low as is reasonably practicable (ALARP).

Based upon the configuration and conditions at the dam, a number of the hazard-failure mode combinations can be ruled out. These are illustrated in Table 7-1 with cells that are hatched. There are a number of failure modes that are possible, however, can be further ruled as improbable because the dam design and operation meet the requirements laid out in the BC Dam Safety Regulation, CDA Guidelines or general industry standards for a structure with the “Very High” DFCC and risks are considered ALARP. These are presented in black text in Table 7-1.

The remaining hazard failure mode combinations are identified as being possible and either reflect deficiencies in meeting the BC Dam Safety Regulation, CDA Guidelines or general industry standards or there is insufficient information to confirm that they meet these requirements. These are illustrated in Table 7-1 with red text.

Table 7-1 can then be used as a visual reference of the state of safety of the dam. The cells with black text illustrate the items that need to be guarded against through the OMS of the dams and planned for the in the Dam Emergency Plan (DEP). The cells with red text illustrate the major items that are current deficiencies that should be addressed to ensure the safety of the dam going forward.

§

Table 7-1: Hazard and Failure Modes Matrix for Elinor South Dam

Element and/or Element Function	Most Basic Functional Failure Characteristics	External Hazards				Internal Hazards (Design, Construction, Maintenance, Operation)			
		Meteorological	Seismic	Reservoir Environment	Human Attack	Water Barrier	Hydraulic Struct.	Mech/Elec.	Infrastructure & Plans
Inadequate installed discharge capacity	Meteorological inflow > buffer + outflow capacity	Improbable – Spillway can safety pass IDF							
Inadequate available discharge capacity	Inadequate reservoir operation (rules not followed)	Improbable – Debris blockage could cause over topping. Mitigated by spillway design, debris boom, and inspection, including monitoring for peat islands and removal.	Improbable - LLO is the only operable equipment and it is not required for flood control.	Improbable - Reservoir slopes are stable; Little debris in reservoir, and debris boom is in place upstream of spillway.		Improbable - LLO is the only operable equipment and it is not required for flood control. Spillway can pass IDF without overtopping of structure.	Improbable - LLO is the only operable equipment and it is not required for flood control.		Improbable - LLO is the only operable equipment and it is not required for flood control. spillway can pass IDF without overtopping of structure.
	Random functional failure on demand	Improbable – no spillway gates. LLO tested regularly.	Improbable – no spillway gates.	Improbable – no spillway gates.	Improbable – no spillway gates.	Improbable – no spillway gates.	Improbable – no spillway gates.	Improbable - No mechanical or electrical equipment required for flood control.	Improbable – no spillway gates.
	Discharge capability not maintained or retained	Improbable - Debris blockage could cause over topping. Mitigated by low debris supply, debris boom, and inspection. Potential for ice blockage is improbable due to operating timeframe. Possible - Vegetation in spillway channel could reduce spillway capacity.		Improbable – Ice jam in front of spillway causing blockage. Grounded ice in lake floats towards spillway. Slope slide from surrounding topography (low probability). Debris blockage could cause over topping. Mitigated by low debris supply, debris boom, and inspection.	Improbable- fixed crest spillway with capacity to pass the IDF. No fence around LLO structure could lead to vandalism of that gate mechanism.	Improbable - Debris blockage could cause over topping. Mitigated by debris supply, debris boom, and inspection.	Improbable		Possible – Excessive growth of vegetation could cause a loss of capacity if not maintained. However, needs to maintain a balance with enough vegetation to ensure channel does not erode away.
Inadequate freeboard	Excessive elevation due to landslide or U/S dam	Improbable –The potential for the wave created by a landslide has not been specifically studied but likely not credible. Possible – Big Meadow Dam is upstream. It is connected by a Diversion only, but an upstream dam should always be considered a hazard if it fails during a metrological event.	Improbable –The potential for the wave created by a landslide has not been specifically studied but likely not credible based on topographic information. Possible – Big Meadow Dam is upstream, which is a hazard if it fails under a seismic event.	Possible – Big Meadow Dam is upstream. It is connected by a Diversion only, but an upstream dam should always be considered a hazard if it fails during a sunny day.		Improbable - Dam could be overtopped and fail if upstream Big Meadow Dam were to fail. However, Big Meadow Dam can pass the PMF therefore risk of failure is low. No landslide hazard identified.			
	Wind-wave dissipation inadequate	Improbable - meets CDA requirements for freeboard for wind wave events for normal and IDF conditions. No riprap layer on upstream face of dam, but this is mitigated by the small size of lake. This failure mode would take time to form and would require repeated events. Review for benching on upper slope, could inspect full slope while empty annually.	Improbable - meets freeboard for wind wave events. Settlement is not expected to be greater than the normal freeboard already available.	Improbable – Freeboard analysis completed. Based on the shape of the reservoir and topography around the reservoir and the fairly short fetch distance, high winds are unlikely to produce waves that overtops the dam.		Improbable – Freeboard analysis completed. Based on the shape of the reservoir and topography around the reservoir and the fairly short fetch distance, high winds cannot produce a wave that overtops the dam.			Improbable - If wind and wave damage is not repaired freeboard could be compromised over time. However wind and wave damage potential is low and regular maintenance will mitigate this.
Safeguards fail to provide timely detection and correction	Operation, maintenance and surveillance fail to detect/prevent hydraulic adequacy	Improbable - due to weekly inspections and lack of mechanical operation. However, meteorological event could make dam inaccessible and therefore prevent the Dam Safety Engineers activities. Helicopter access should be considered in an emergency	Improbable - Likely no road access to the site following a seismic event due to loss of road. However, there are likely locations suitable for helicopter landing.	Improbable - Good OMS procedures and little expected influence from reservoir environment.		Improbable - due to weekly inspections, and lack of mechanical operation.			Improbable - due to weekly inspections and lack of mechanical operation.

Element and/or Element Function	Most Basic Functional Failure Characteristics	External Hazards				Internal Hazards (Design, Construction, Maintenance, Operation)			
		Meteorological	Seismic	Reservoir Environment	Human Attack	Water Barrier	Hydraulic Struct.	Mech/Elec.	Infrastructure & Plans
	Operation, maintenance and surveillance fail to detect poor dam performance	Possible - Seepage is occurring during normal water level, which may worsen during a high water table. This should be detected and responded appropriately and in a timely fashion. However, meteorological event could make dam inaccessible and therefore prevent the Dam Safety Engineers activities. Helicopter access should be considered in an emergency. Mitigated by weekly inspections.	Possible - If distress in dam occurs after a seismic event and the LLO is damaged, there is currently no method or procedure in place to lower the reservoir. Consideration should be given to a portable siphon system to lower the reservoir in case of emergency.	Improbable - Good OMS procedures and little expected influence from reservoir environment.		Possible - No instrumentation or seepage monitoring. Mitigated by weekly inspections. Additional instrumentation is recommended.			Possible - Insufficient instrumentation or seepage monitoring. Mitigated by weekly inspections. Additional instrumentation is recommended
Stability under applied loads	Mass movement (external stability:- displacement, tilting, seismic resistance)	Improbable - Dam meets stability requirements.	Possible - Dam meets seismic stability requirements. However, its post-seismic resistance and liquefaction behaviour is not known which require investigation and assessment.	Improbable - A landslide induced or seiche wave large enough to overtop the dam is not considered to be a highlighted hazard. Possible - Big Meadow Dam is upstream. It is connected by a Diversion only, but an upstream dam should always be considered a hazard if it fails during a seismic event.		Improbable - Dam meets seismic stability requirements. Geotechnical investigation and assessment are needed to confirm the assumptions.			Improbable - Regular inspections. Geotechnical investigation and assessment are needed to confirm the assumptions.
	Loss of support (foundation or abutment failure)	Improbable - Dam meets stability requirements.	Possible - However, its post-seismic resistance and liquefaction behaviour is not known which require investigation and assessment.			Improbable - Dam meets stability requirements.			Improbable - Regular inspections. Geotechnical investigation and assessment are needed to confirm the assumptions.
Watertightness	Seepage around interfaces (abutments, foundation, water stops)	Possible - Deteriorated foundation and boiling may happen in the future during IDF.	Possible - Seepage and internal piping analyses not completed to date followed by investigation.			Possible - Considerable seepage is occurring. Materials internal stability, filter compatibility are not known which require investigation and assessment.			Possible - Seepage/turbidity quantity monitoring and pore water pressure by piezometers is not currently being conducted.
	Through dam seepage control failure (filters, drains, pumps)	Possible - Deteriorated foundation and boiling may happen in the future during IDF.	Possible - Seepage and internal piping analyses not completed to date followed by investigation.			Possible - Considerable seepage is occurring. Materials internal stability, filter compatibility are not known which require investigation and assessment.			Possible - Seepage/turbidity quantity monitoring and pore water pressure measurement by piezometers is not currently being conducted
Durability/ cracking	Structural weakening (internal erosion, AAR, crushing, gradual strength loss)	Possible - Likely not credible under IDF. Requires future investigation and instrumentation.	Possible - Dam foundation susceptible to liquefaction. Investigation and assessment needed.			Possible - Dam foundation, upstream core and shell materials might be susceptible. Investigation and assessment needed.			Improbable - Regular and post-event inspections.
	Instantaneous change of state (static liquefaction, hydraulic fracture, seismic cracking)	Improbable	Possible - Dam foundation susceptible to liquefaction. Investigation and assessment needed.			Possible - Dam foundation susceptible to liquefaction. Investigation and assessment needed.			Improbable - Regular and post-event inspections.

7.2 Hydrotechnical Assessment

7.2.1 Review of Hydrological Studies

The flood hydrology associated with the Naramata Dams basin was developed during the 2010 Hydrotechnical Assessment of the Naramata Dams [EBA Engineering Consultants, 2010], and updated as part of this study, as detailed under separate cover in Naramata Dam Breach Assessment and Inundation Mapping (2021).

Additional data collected at the active gauges since the 2010 assessment was included in Hatch’s assessment. Although results of the 2010 analysis were not presented in the previous report, results of the updated flood frequency analysis are found in Table 7-2.

Table 7-2: Flood Frequency Analysis

Return Period (years)	Current Flood Frequency Analysis: Peak Flow (m ³ /s)
2	1.0
5	1.3
10	1.5
20	1.6
50	1.8
100	1.9
200	2.0
1000	2.3

A PMF analysis was completed for the Elinor reservoir. The procedures used to assess the IDF for the past studies are generally acceptable for such a small catchment without available local gauge information. Given the lack of available data it is unlikely that a more rigorous analysis could be performed that would yield more accurate results than those obtained. Therefore, the same analysis was completed, including gauge data collected since the previous assessment.

The PMF Estimator for British Columbia provides the following equation for the Okanagan region within Zone 12B for watershed areas less than 8320 km² [Abrahamson & Pentland, 2010]:

$$Q = 2.1086A^{0.9240}$$

Where Q is the probable maximum flood in m³/s and A is the area of the watershed in km². The results are presented in Table 7-3.

Table 7-3: PMF Peak Flows

Dam	Watershed Area (km ²)	Peak PMF (m ³ /s)
Elinor Lake South Dam	1.3	2.7

7.2.2 **Flood Operating Rules**

The Naramata Dams watershed operating system is detailed in the companion report: Naramata Dam Breach Assessment and Inundation Mapping (2021) a summary of the operation of Elinor South Dam is provided as follows.

Aside from the operation of the Chute Creek Diversion to assist in the filling of the Elinor Reservoir, the only operable portion of the Elinor South Dam is the 0.457 m diameter low-level riparian conduit structure described in Section 2. Its capacity has not been assessed. However, its capacity is not significant during a large flood event, compared to the volume of flow that can be passed by the spillway.

The previous Elinor Dams OMS and EPP (2017) suggests that if the run-off water is excessive, the outlet gate can be opened to relieve some of the inflow. In general, due to the design of these low flow outlets for more normal reservoir water levels and backwater conditions as well as the relatively small capacity compared to spill capacity during a flood this type of action is NOT recommended. If operated during a major flood there are dangers of excessive erosion downstream of the conduit as well as damage to the conduit and gate due to air demand exceeding available venting at the structure. As the spillway can safely pass flows in excess of the IDF operation of the conduit during a flood should not be required.

7.2.3 **Discharge Capacity**

There are two (2) structures that provide discharge capacity at Elinor South Dam. These are the low level outlet and the uncontrolled concrete overflow spillway. Both structures were reviewed to confirm that the assumptions made in their design are appropriate.

7.2.3.1 **Low Level Outlet**

The low level outlet is described in Section 2. The main use of the low level outlet is to pass flow from the lake to maintain a minimum downstream riparian flow. The Elinor Dams OMS and EPP (2017) suggests that if the run-off water is excessive, the outlet gate can be opened to relieve some of the inflow. However, as stated above this runs the risk of damaging the structure and should not be used in this fashion. It is not required as the IDF can be accommodated through the spillway. A rating curve was not found for this structure. The outlet channel appears to have required excavation into natural ground for nearly the entire channel to Naramata Lake (as inferred from the Lidar data). To note, the Elinor South LLO invert of 1272.4 m is only 0.45 m higher than the Naramata FSL of 1271.95m, therefore backwater effects at Elinor South Dam may be realized for large inflows at Naramata Dam.

7.2.3.2 Spillway

Elinor South Dam's spillway is an uncontrolled concrete overflow weir that discharges into a channel that is excavated to a point approximately 100 m downstream, where it then appears to daylight to a natural channel that terminates at the northeast tip of Naramata Lake (as inferred from the Lidar data). The spillway is approximately 3 m wide, and although narrower than the 4 m recommended for a high or above classification structure the presence of a debris boom and capacity in excess of what is required for the IDF limits the risk of debris reducing discharge capacity and causing overtopping of the dam.

A design spillway rating curve was not found within the available data collected during the study. The discharge capacity was assessed in the Hydrotechnical Assessment of Naramata Dams [EBA, 2010]. The broad-crested weir equation was used along with the geometry of the spillway, assuming a discharge coefficient of 1.65. A stage discharge curve for Elinor South spillway is shown in Figure 7-1.




Figure 7-1: Elinor South Dam Spillway Stage-Discharge Curve

The spillway intake and outlet includes an excavated channel lined with masonry rocks with no mortar. During the IDF, 2.4 m³/s with 0.53 m of head and a velocity of approximately 1.2 m/s will pass over the spillway. The lined spillway channel bottom should be sufficiently protected from erosion. Due to the prudent operation of the reservoirs level and likely infrequent use of the spillway, it is recommended that any damage that occurs during such an event be repaired as soon as possible following a large event.

7.2.4 **Flood Passage Capability**

The discharge capacity of the Elinor South Dam spillway was assessed in the dam breach study by Hatch (2020), which is summarized in a stand-alone report.

A hydraulic model was set up to route the flood through the system, and concluded that the spillway can pass the IDF (equivalent to an Annual Exceedance Probability of 1/3 between 1/1,000 and PMF, with a peak inflow of 2.4 m³/s). The maximum reservoir water level during this event would be approximately 1277.08 m, which is 0.36 m below the minimum dam crest.

7.2.5 **Freeboard**

The B.C. Dam Safety Regulation [B.C. Reg 44/2016] under the Water Sustainability Act does not speak directly to freeboard requirements for dams. However, according to the CDA Guidelines [CDA, 2007a], embankment structures are required to meet the following wind/wave criteria.

- No overtopping by 95% of the waves caused by the most critical wind with a frequency of 1:1,000 year when the reservoir is at its maximum normal elevation.
- No overtopping by 95% of the waves caused by the most critical wind with a frequency of 1:2 year when the reservoir is at its maximum extreme level during the passage of the IDF.

In BC, the document that speaks to freeboard requirements specifically is the FLNRO, Plan Submission Requirements for the Construction and Rehabilitation of Small Dams, 2018. This document provides the following requirements:

“Two types of freeboard are discussed below; normal and minimum. Regardless of which freeboard is used in the dam design, both require the spillway be able pass the IDF (see section on Spillway above).

(a) Normal Freeboard (or Gross Freeboard) is the difference of elevation between the lowest elevation of the top of the dam (or top of impervious core) and the maximum reservoir operating level (full supply level, often the spillway sill elevation).

(b) Minimum Freeboard (or Net Freeboard) is the difference of elevation between the lowest elevation of the top of the dam (or top of impervious core) and the maximum water level of the reservoir should the Inflow Design Flood (IDF) occur.

To prevent overtopping and provide redundancies in the dam design, the following freeboard standards shall be applied:

- The normal freeboard shall be at least 1.0 m in combination with a spillway width of at least 4.0 m.
- If the design engineer wants to present a case for a spillway width of less than 4.0 m wide, the minimum freeboard shall be at least 1.0 m. A spillway width of less than 4.0 m wide is not recommended for High and Very High dam failure consequence classification dams.

In addition, the Canadian Dam Association’s Dam Safety Guideline’s Technical Bulletin, Section 6.0 - Hydrotechnical Considerations for Dam Safety, should be consulted.”

Calculations for these conditions were carried out on Elinor Lake to determine if adequate freeboard exists.

During the site inspection, observations were made that indicated that the 1 m requirement may in fact be overly conservative for this specific dam. It was noted that the maximum effective fetch in which wind waves can be developed in the lake is less than 370 m (very short) and the lake is located in a valley with less exposure to wind. It is also understood that the 1 m requirement is largely a ‘rule of thumb’ based upon guidance provided by the United States Bureau of Reclamation as well as other jurisdictions. This or a similar rule are applied in many jurisdictions across Canada where more sophisticated analysis is not performed. For these reasons, it was deemed reasonable to perform a standard wind/wave assessment following the CDA Guidelines to determine the level of conservatism in the 1 m requirements and whether a lower standard may be acceptable.

First, fetch lengths for each cardinal and intercardinal wind direction for the most exposed location of Elinor Lake South Dam was determined using the methodology specified in the USACE Coastal Engineering Manual (CEM) 2011. Calculated critical fetches for each cardinal and intercardinal direction are shown in **Table 7-4**.

Table 7-4: Elinor South Dam Effective Fetch Calculations

Direction	Length (m)
N	368
NE	91
E	41
SE	9
S	5
SW	13
W	36
NW	245

Wind speed and direction data was taken from the Environment Canada climate gauge located at Summerland CS. This gauge is located approximately 15 km from Elinor South Dam and has data from 1994 - 2020. This gauge was chosen over others in the area because it had the longest period of record within the vicinity of Elinor Lake.

A frequency analysis was conducted on the wind data to determine wind speeds for several annual exceedance probabilities and for each intercardinal direction. Annual maximum one-hour wind speed values were fitted to a Gumbel statistical distribution to determine the wind speeds associated with various return periods. The results of the frequency analysis are summarized in Table 7-5.

Table 7-5: Wind Velocities (km/h)

Return Period	Direction							
	N	NE	E	SE	S	SW	W	NW
2	25	17	17	36	46	21	24	29
10	32	23	22	43	55	27	30	35
20	35	26	23	45	58	29	33	37
30	36	27	24	47	60	30	35	38
50	38	29	25	49	62	31	36	39
100	41	31	27	51	66	33	39	41
1,000	50	39	32	60	76	40	47	48

Over-land wind speeds are converted to over-water wind speeds using correction factors based on empirical relationships found in the CEM [USACE, 2011]. These factors include corrections for non-standard anemometer elevation, minimum time required to form fetch limited waves, air-water temperature difference and surface roughness relationships.

To calculate wave characteristics the water depth was assumed to be 4.1 m.

Wave characteristics were calculated for an IDF fetch combined with a 1:2-year wind event and the FSL fetch combined with a 1:1,000-year wind for all intercardinal directions to determine the critical wave condition. It was found that the largest fetch length and critical wave conditions were in the N direction in all case.

In addition, the wave characteristics were calculated for the 1:100-year wind event combined with the FSL shoreline fetch lengths to assess riprap requirements.

Wave height, wave period, wind setup and wave runup which are exceeded by 5% of the incoming waves were calculated using the equations found in the CEM.

To calculate wave runup, the dam slope was taken to be 2.5H:1V. For wind setup (wind tide), the maximum length of the reservoir that was considered was determined to be 0.37 km. The impact of wind setup was negligible (approximately 1 cm during a 1000 year wind).

The still water level for the extreme wind condition at FSL was assumed to be the same as the spillway crest elevation of 1276.55 m. For freeboard calculations, the still water level for the IDF was taken as 1277.08 m based on reservoir routing results shown in Section 7.2.4.

Table 7-6 shows the wind setup and wave runup results obtained using the CEM method.

Table 7-6: Elinor South Dam Freeboard Assessment Results (CEM)

Case	Dir	Wind Event Return Period	Fetch (km)	Over Water Wind Speed (km/hr)	Still Water Level (m)	5% Wave Runup (m)	Fetch for Setup (km)	Wind Setup (m)	Total Wind Effects (m)	Maximum Water Level Including Wind Effects (m)	Structure Design Crest Elevation (m)	Freeboard Remaining (m)
Extreme Wind	N	1:1,000	0.37	50.12	1276.55	0.23	0.37	0.01	0.24	1276.79	1277.44	0.65
1/3 between 1000-year and PMF Flood Passage	N	1:2	0.37	24.72	1277.08	0.1	0.37	0.00	0.1	1277.18	1277.44	0.26

As shown, freeboard requirements are governed by the IDF case. The analysis shows that the minimum required crest elevation to account for wind/wave effect is 1277.18 m. Based on the 2010 Topographic Survey [EBA], the minimum crest elevation of the dams is 1277.44 m, meaning that there is 0.26 m of additional freeboard available after accounting for wind/wave effects. Therefore, by the CDA guidelines the freeboard to the lowest portion of the dam crest is adequate. The only issue remains that this does not meet the 1 m minimum recommended by the Plan Submission Requirements for the Construction and Rehabilitation of Small Dams [FLNRO, 2018].

Given the results of this analysis it is our recommendation that RDOS open a dialogue with BC Dam Safety to discuss whether the freeboard analysis performed would be acceptable in lieu of meeting the minimum 1 m requirement (see Issue ES-7 in Table 13-1).

7.2.6 **Riprap**

Based on the wind and wave analysis that was carried out for the freeboard portion of this review, Hatch also completed an assessment of the required riprap protection based on the CEM method and Hudson equation for the Elinor Lake South Dam and compared the results to what was observed during the site visit.

Key assumptions that were used for the calculation of required riprap sizing included:

- A riprap density of 2,700 kg/m³
- A Kd value of 2.2 was used to size the riprap
- The maximum mass of rock was defined as four times M₅₀ (mass of the median rock) and the minimum mass of rock was defined as 0.125 M₅₀.

Based on these values, required riprap rock sizes and thicknesses were calculated for a number of return periods. The resulting minimum, maximum, and D₅₀ (median rock diameter) values are shown in Table 7-7.

Table 7-7: CEM Riprap Requirements

Return Period	Diameter of Riprap (m)			Thickness of Riprap (m)
	Minimum	Maximum	D ₅₀	
2	0.0	0.1	0.1	0.3
10	0.0	0.1	0.1	0.3
20	0.0	0.1	0.1	0.3
30	0.0	0.2	0.1	0.3
50	0.1	0.2	0.1	0.3
100	0.1	0.2	0.1	0.3
1,000	0.1	0.2	0.1	0.3

The CDA is not prescriptive on a specific return period required for riprap protection. Within the industry generally the return period of wind events used varies between a 1:10 (USACE) to 1:100 (USBR, USACE, SEBJ) to 1:1000 (SEBJ for tolerable damage). Generally speaking, most guidelines agree that a 1 in 100-year wind is appropriate for riprap protection. Based on the review in Table 7-7, the riprap layer should be 0.3 m thick with a D_{50} of 0.1 m (if using the assumptions provided in the above analysis) to resist wind generated waves up to a 100-year event. Since there does not appear to be existing riprap, the condition of the upstream face of the dam should continue to be monitored as part of RDOS's regular surveillance and maintenance program and any erosion problems identified and repaired in a timely fashion. In addition, the size of the riprap protection needed is very small, this is a good indicator that riprap protection is not a large concern for this structure and erosion due to wind wave action can be adequately addressed through regular inspection and repair as needed. (see Issue No. ES-13 in Table 13-1).

7.2.7 *Ice and Debris*

No records of debris problems at the structure have been found in the documentation. It has been noted that peat islands can be found in Elinor Lake, but that campers and hunters typically remove them for their own use.

A debris boom is in place upstream of the spillway to prevent debris accumulation at the site. Debris should be removed from this boom in a timely fashion in order to prevent excessive buildup and potential failure of the boom during a large flood event.

Due to the annual emptying of the reservoir prior to winter and its location far below the normal operating reservoir level, the intake is unlikely to experience any ice or debris issues.

7.3 **Structural Assessment**

7.3.1 *General*

As part of the DSR, the concrete structures at Elinor South Dam site were reviewed for their condition and capability to perform their intended function. Apart from the main embankment dam, the other water control structures include a concrete spillway weir, an intake structure and an outlet structure.

The intake and outlet structures are relative low height structures with wide and stable base. Since these structures have performed reasonably well over their design life, the stability of these structures is not a concern, as long as they are inspected and well maintained.

The existing spillway weir is a concrete structure installed on the left abutment. There were no design details of the structure available from existing drawings. From the site visit, the concrete weir appears to be in stable condition as the weir is keyed into the riprap on both the upstream and downstream of the weir (see Photo A11), and with riprap lining along the sides of the channel. The original structure had a provision to install stoplogs however the stoplogs are not used at this site and the spillway essentially operates as a free overflow section with no control elements such as gates or stoplogs.

A cursory review of the floatation/uplift stability of the spillway apron slab was performed. The floatation/uplift of the apron slab is not deemed a concern.

7.4 Geotechnical Assessment

As part of the 2020 DSR, Hatch conducted a review of the geotechnical conditions of Elinor Lake South Dam. This was limited to a review of the available information on the original construction drawings and site geology. No geotechnical investigation was conducted at the dam site before or after the construction. It should be noted that no design report exists which describes the basis of original design. This background review along with the site visit observations made on July 9, 2020 (photos provided in Appendix A) were used to determine appropriate ground properties for the seepage and stability analyses. In the absence of information, Hatch has made acceptable assumptions and provided recommendations for further investigation.

7.4.1 Geology

As described by EBA (2010), the Geological Survey of Canada Map Surficial Geology Kootenay Lake (1984) indicates that surficial soil at the Elinor South Dam site is anticipated to be comprised of Sandy Till overlying crystalline metamorphic bedrock. The Sandy Till is described as a olive grey, grey to pale grey, weakly calcareous to non-calcareous loamy sand, sandy loam and loam, generally gravelly, cobbly or bouldery. It is mainly massive but may contain lenses of stratified sediments. It occurs as a blanket deposit with surface relief due to the shape of the underlying surface. The thickness of the soil unit varies from up to 30 m in the valley bottoms to no more than 5 m thick.

Clast lithologies reflect local bedrock which comprises mainly crystalline metamorphic and granitic rock. The surficial geology in the area of the Naramata dams is shown on EBA (2010), Figure 1.

7.4.2 Seismicity

The Elinor Lake South Dam has been classified as a “High” consequence dam based on incremental consequences of failure. Under this consequence category, the seismic stability of the dam should be evaluated under an earthquake with a return period of 1/2,475 years, as described in the CDA Dam Safety Guidelines (CDA, 2013 revision).

The foundation at the dam site is expected to be comprised of glacial till not deeper than 5 m. Therefore, site Class C conditions (foundations on Very Dense Soil and Soft Rock) are considered appropriate for the Naramata dam sites.

A 2015 National Building Code of Canada (NBCC) Seismic Hazard Calculation provides an estimated Peak Ground Acceleration (PGA) for the events up to 2,475 year events. Appendix B contains the 2015 NBCC seismic hazard assessment for the Naramata Lake Dam, which is also used for the Elinor South Dam.

The NBCC Seismic Hazard Calculator provides a PGA of 0.070 g for the 1/2,475 year event. Correspondingly, a PGA of 0.070g was used in the stability analyses of the Elinor Lake South

Dam, equivalent to full PGA value. It should be noted that this value is smaller than the PGA of 0.138 g, as was estimated and selected during 2010 DSR (EBA, 2010), which is due to refinements to the seismic model used in subsequent editions of the NBCC.

Table 7-8: National Building Code of Canada (NBCC) Seismic Hazard

Annual Exceedance Probability	NBCC 2005	NBCC 2010	NBCC 2015
1/100	0.035g	0.035g	0.010g
1/475	0.073g	0.073g	0.029g
1/1000	0.098g	0.098g	0.044g
Selected Value – 1/2475 year	0.138g	0.138g	0.070g

7.4.3 Preliminary and Supplementary Field Investigations

No geotechnical investigation was carried out at the location of the Elinor South Dam. Conducting a detailed geotechnical investigation is recommended for detailed assessment of the embankment during normal and extreme load combinations. Such investigation should include a combination of drilling intrusive test holes (with Standard Penetration Testing (SPT)) and pushing Cone Penetration Testing (CPT) probes. Test holes should be extended enough into foundation materials for the foundation ground characterization. Laboratory testing should also be carried out for detailed classification of the embankment and foundation materials. A few piezometers should be installed upon completion of the test holes for long-term monitoring of the pore water pressure inside the embankment.

7.4.3.1 Embankment Dam

The historical drawing (No. 1316), dated December 1966, shows that the embankment dam was designed with two zones, namely impervious clay core and granular shell materials (OMS, 2017). A typical cross section of the Naramata Dam is depicted in Figure 7-2.

The existing drawings of the South Dam indicate that it has a 2.5H:1V upstream slope and 3.5H:1V downstream slope. The downstream slope geometry was confirmed via the 2012 topographic survey. The current overall downstream slope is approximately 3.5H:1V, with some local steepening, particularly around the low level outlet drain. The slopes near both abutments are shallower than at the drain location. The upstream slope geometry has not been confirmed in detailed, it is assumed that it has not changed from the design 2.5H:1V slope.

The central core of the dam is constructed with clay core materials with vertical side slopes which is considered non-conventional which could be due to the lack of considerable quantity of clay materials at the site. The cores are generally constructed with inclined slopes so that no core/shell separation and sliding take place and the core materials experience vertical positive stress from the shell materials. As shown in Figure 7-2 the clay core is extended into foundation materials, however, little information exists on the foundation material, embedment core depth, or foundation excavation footprints.

Following inspection of the South Dam in 1991, which noted significant seepage along the toe of the embankment, the installation of a 1.0 m deep granular toe drain incorporating a 0.3 m diameter perforated pipe was recommended; however it is unknown if these works were undertaken (OMS, 2017).




Figure 7-2: Typical Cross Section of the Elinor South Embankment Dam

7.4.3.2 Spillway

The spillway was constructed on the left abutment of the Elinor South Dam on the overburden material. The channel appears to be lined with masonry rock and on the sidewalls. The spillway sidewalls were found to be generally in good condition with no sign of distress (Okanagan Survey, 2012). The existing survey does not provide details of the side slopes inclination. Hatch recommends a detailed condition assessment of the spillway masonry rock.

Figure 7-3 illustrates the spillway site plan, channel, and sill as surveyed by Okanagan Survey (2012) located on the left abutment of the Elinor South Dam. A safety boom exists upstream of the spillway channel which drains to the Naramata Reservoir downstream. Hatch does not anticipate flow induced erosion in this channel. The slopes on the sides of the channel were found stable and consistent with earthen channels. No drawing exists providing details of the channel slopes and materials.




Figure 7-3: Spillway Plan at Elinor South Dam Site – (Okanagan Survey, 2012)

7.4.3.3 *Foundation*

No information exists related to the foundation material type or bedrock depth. As noted in general geology Section 7.4.1, the foundation is anticipated to be comprised of Sandy Till overlying crystalline metamorphic bedrock.

7.4.3.4 *Riparian Conduit*

An 18 inch (457.2 mm) diameter steel discharge conduit was grouted into the original concrete culvert and extended at the downstream slope of the South Dam in 1959, however, it is unknown if there was a modification of the downstream slope at this time. Currently, considerable seepage flow can be observed on the right side of the outlet structure. Seepage quantity is less on the left side of the outlet structure.

7.4.4 **Geotechnical Seepage and Stability Assessment**

A geotechnical assessment of seepage and slope stability of the dam were undertaken as part of this DSR. A review of available information pertaining to the material properties, cross section and construction history of the dam were carried out prior to the analyses. The following drawings and data provided by RDOS were used to develop the cross-sectional geometries, and material properties for the sections analyzed:

- Water Rights Branch. Naramata Irrigation District – Eleanor Lake Dam – Details of Culvert Gate Repairs. December 1966.
- Okanagan Survey and Design Ltd. Elinor Lake – North Dam – Site Topography (EN-01). July 2012.

7.4.4.1 *Material Properties*

There is very little information available regarding properties of the embankment and foundation materials at Elinor Lake South Dam. Due to the limited background data, a preliminary analysis was conducted using assumed values. The values were selected with reference to typical published values for each type of material, and from results of historical and more recent geotechnical investigations conducted at Big Meadow Lake Dam and Naramata Lake Dam. The embankment was considered to consist of two zones, as described in Section 7.4.3:

- Central impervious zone (silty clay)
- Granular shell fill

Additionally, the foundation material was assumed as sandy till.

The saturated permeability for each material was assumed for use in the seepage assessment. The selected permeability values for each material are listed in Table 2-1.

Table 7-9: Material Permeabilities

Material Name	Saturated Permeability (m/sec)
Silty Clay	$2.5 * 10^{-8}$
Shell Fill	$5.0 * 10^{-5}$
Foundation – Sandy Till	$5.0 * 10^{-6}$

The unit weights and material strength parameters selected for each material are shown in Table 7-10.

Table 7-10: Material Properties – Mohr-Coulomb Strength Parameters

Materials	Unit Weight (kN/m ³)	Friction Angle (degrees)	Cohesion (kPa)
Clay Core	18	28	0
Shell Fill	20	33	0
Foundation – Sandy Till	21	32	0

7.4.4.2 *Stability Criteria*

The required minimum factors of safety for a dam classified as “High” consequence, as outlined in the 2007 CDA Guidelines (2013 Revision) are provided in Table 7-11.

Table 7-11: Required Minimum Factors of Safety

Load Condition	Required Minimum Factor of Safety	Slope	Resource
Steady State Seepage with Full Supply Level (FSL)	1.5	Upstream and Downstream	CDA
Steady State Seepage with Inflow Design Flood (IDF)	1.3	Upstream and Downstream	CDA
Rapid Drawdown	1.2 – 1.3	Upstream	CDA
Earthquake (FSL, Sh)	1.0	Upstream and Downstream	CDA

7.4.4.3 Model Geometry

The geometries of the embankment were determined from available drawings, reports and survey data. The critical section used for the seepage and slope stability analyses was selected at the tallest dam section. A plan view sketch of the section chosen for analysis is presented in Figure 7-4, and the cross-section as used in the analysis is presented in Figure 7-5.




Figure 7-4: Location of Seepage and Stability Cross-Section (Okanagan Survey, 2012)




Figure 7-5: Modelled Critical Cross Section

The critical geometries used in the stability analyses for Elinor Lake North Dam are presented in Table 7-12.

Table 7-12: Elinor Lake South Dam Selected Section Properties

Structure	Embankment Section
Height	Overall: 4.6 m
Crest Width	2.65 m
Upstream Slope	Overall: 3.5H:1V
Downstream Slope	Overall: 2.5:1V
Dam Crest Elevation	1277.7 m

7.4.4.4 Seepage Analysis

The seepage analyses were performed using SEEP/W software developed by GEO-SLOPE International Ltd. Version 10.1.1.18972. The program was used to generate the pore pressure distribution used for evaluating the exit gradients of the embankment. For evaluating the slope stability of the embankment, the porewater pressures developed in the SEEP/W program were interpreted to create a phreatic surface line in the SLOPE/W program.

The seepage analysis was performed for steady-state conditions under the following reservoir supply levels:

- Full supply level (FSL): 1276.55 m
- Inflow Design Flood (IDF): 1277.08 m.

A summary of the results of the seepage analyses are shown in Table 7-13. The complete results of each of the simulations completed for the seepage analyses of Elinor Lake South Dam are presented in detail in Appendix B.

Table 7-13: Results for Seepage Analyses

Load Case	Flow Rate per meter (m ³ /day/m)	Maximum Exit Gradient	Factor of Safety Against Piping
FSL	0.89	0.300	3.33
IDF	N/A ¹	0.305	3.28

¹ The IDF is a temporary condition; the flow rate will change as the flood level changes, and can not be fully represented by the steady-state seepage model. Thus, the flow rate has not been reported.

Piping potential for the foundation has been assessed based on exit hydraulic gradients at the toe of the dam. Water that percolates through earth dams and their foundations can carry soil particles that are free to migrate. The seepage forces tend to cause the erodible soil or soft rock to move towards the downstream face of the dam.

The preceding exit gradient estimates represent the total head loss per unit length of the seepage path. High exit gradients may contribute to boiling or piping near the downstream toe. The critical hydraulic gradient (i_c) is defined as the hydraulic gradient at which boiling or piping (loss of soil strength initiating erosion) occurs and generally ranges between 0.85 to 1.1 (for most soils). The factor of safety against piping is therefore calculated as the ratio between the critical and estimated exit hydraulic gradients, as follows:

$$FoS_{piping} = \frac{i_c}{i}$$

Allowable factors of safety against piping typically range between 2 and 4 as outlined in Table 7-14.

Table 7-14: Summary of Allowable Exit Gradients and Factors of Safety

Reference	Minimum Required FoS	Approximate Maximum Gradient	Remarks
USACE (2005)	2	0.5	Sand boils generally occurred at gradients between 0.5 and 0.8 based on historical observations.
USBR (2011)	3 – 4	0.25 – 0.33	Factor of safety of 4 recommended for remediation of dams where high exit gradients exist.

The results of the seepage analysis indicate that the exit gradients at the downstream toe are elevated. The factor of safety against piping is approximately 3.3, which is marginal based on the published guidance above. This result is consistent with the observations of seepage downstream of the dam. The results of the seepage analysis are based on assumed material parameters, due to the lack of information available regarding the embankment and foundation materials. Results of the semi-quantitative piping risk assessment in Section 7.4.5.5 should also be considered, showing that the piping risk is near the tolerable threshold. A combination of these analyses and observations supports the conclusion that the overall factor of safety of exit gradients is marginally unacceptable. As such, a geotechnical

investigation and assessment should be completed to obtain more accurate material parameters and confirm these findings. It is anticipated that the results of such an assessment would lead to recommendations for remedial works such as a toe berm or drain.

7.4.4.5 *Stability Analysis*

The stability analyses were performed using SLOPE/W software developed by GEO-SLOPE International Ltd. Version 10.1.1.18972. The program uses the limit state equilibrium technique to model heterogeneous soil types, complex stratigraphic and slip surface geometry, and variable porewater pressure conditions using a large selection of soil strength models. Stability analyses for the Elinor Lake North Dam were performed based on effective stress analysis. The Morgenstern-Price method of slices with a half-sine function was selected for the inter-slice force function since this method satisfies both moment and force equilibrium.

The Entry and Exit method was used to generate slip surfaces, which calculates circular slip surfaces extending between a series of points on the upper and lower portions of a slope, and with a series of increasing radii.

As noted above, the embankment section utilized interpreted pore water pressure conditions from the results of the SEEP/W analysis.

Load cases for the stability analyses were selected based on CDA Dam Safety Guidelines (CDA, 2013a). The design loads for the flood and seismic conditions were determined based on the methodologies discussed in Sections 7.2 and 7.4.2, respectively. The slope stability load cases are summarized in Table 7-15.

Table 7-15: Loading Conditions Elinor Lake South Dam Section

Load Case	Operating Conditions	Remarks
LC-1	Normal Load Condition - Full Supply Level (FSL)	Reservoir Elevation = 1276.45
LC-2	Flood Condition - Inflow Design Flood (IDF)	Reservoir Elevation = 1277.08 m
LC-3	Rapid Drawdown (RDD)	Reservoir Elevation = 1273.25 m*
LC-4	Seismic	Horizontal seismic coefficient (kh) of 0.07g corresponding to the full PGA of the EDGM**.

* Corresponds to elevation of low-level outlet.

** EDGM defined as the 1:2,475 year seismic event (CDA, 2013a)

For the rapid drawdown case, the phreatic surface was selected based on Hatch's engineering judgement due to the limited available information. The phreatic surface is assumed to follow the Full Supply Level steady-state phreatic surface in the core and downstream shell. In the upstream shell, the phreatic surface is assumed as a straight line extending from the upstream toe to upstream side of the core. The model conditions are shown in Figure 7-6.




Figure 7-6: Rapid Drawdown Model Conditions

The Rapid Drawdown case is a transient condition, and the pore water pressure conditions occurring in this case depend on the speed with which the reservoir is drawn down and the permeability of the embankment materials. A more permeable embankment and slower rate of drawdown will result in a greater factor of safety for slope stability. The upstream shell of the dam is constructed of relatively free-draining granular material. Since there is no information available regarding the material properties, the phreatic surface was selected conservatively, assuming that the embankment material is much less permeable than expected. The actual phreatic surface in a rapid drawdown event is expected to be lower and less critical than the case analyzed. There have also been no evidence of upstream slope instability. As such, the rapid drawdown case is not expected to present critical stability issues.

A summary of the results of the stability analyses are shown in Table 7-16. The complete results of the slope stability analyses are presented in Appendix D.

Table 7-16: Results of Stability Analyses

Load Condition	Required Minimum Factor of Safety	Factor of Safety	
		Normal Loading Conditions	
		Upstream	Downstream
LC-1 (FSL)	1.50	1.69	2.17
LC-2 (IDF)	1.30	1.76	2.17
LC-3 (RDD)	1.20	1.31	N/A
LC-4 (Seismic)	1.00	1.26	1.67

Overall, the calculated factors of safety for upstream and downstream for each load case exceed the minimum recommended values as indicated by 2007 CDA Guidelines (2013 Revision).

7.4.5 Geotechnical Considerations

Geotechnical considerations related to the dam safety of the Elinor Lake South Dam are discussed in the following sections.

7.4.5.1 Liquefaction Potential

Available information regarding subsurface conditions was not available at the time of writing this report. Accordingly, no quantitative liquefaction assessments were undertaken for Elinor Lake North dam. A seismic assessment of the dam is recommended due to its “Very High” consequence classification and limited embankment and foundation information.

A geotechnical subsurface investigation is recommended to characterize the embankment and foundation materials, and provide relevant information for a liquefaction triggering assessment (See Issue ES-5 in Table 13-1).

7.4.5.2 Post-seismic

The expected performance of the dam following the design seismic event is currently unknown. The post-seismic stability will depend on the extent of liquefaction, particularly within the dam’s granular shell. Post-seismic stability considering residual strength parameters should be assessed using results from a future geotechnical investigation and liquefaction assessment (see Issues ES-2c and ES-5 in Table 13-1).

7.4.5.3 Internal Stability and Material Compatibility

Seepage flows through granular materials in an embankment dam can cause fine particles in the material to be eroded away, leaving only coarser grained particles and higher proportion of voids. The susceptibility of a material to this phenomenon is referred to as internal stability.

Internal stability is assessed by analysis of the grain size distribution curves obtained from a laboratory sieve test of embankment materials. No such grain size distribution curves are available for the Elinor Lake South Dam. This testing should be conducted in a future geotechnical investigation and an internal stability analysis subsequently completed (see Issues ES-2c and ES-5 in Table 13-1).

An additional factor affecting risk of piping is the compatibility between different zones of the embankment. This is defined by the ratios between certain index grain sizes of materials in adjacent embankment zones, such as the clay core and granular shell. This should also be assessed for the Elinor Lake South Dam upon completion of a geotechnical investigation and laboratory testing.

7.4.5.4 Instrumentation

There is currently limited instrumentation installed at the Elinor Lake South Dam. Considering the consequence classification of the dam, instrumentation should be installed and monitored regularly, consisting of at least one piezometer and seepage weirs (see Issues ES-2d and ES-12 in Table 13-1).

7.4.5.5 Piping Potential

EBA [2010] carry out an assessment of piping Failure Risk Assessment at the Elinor Lake North and South Dams. Past inspections have not specifically identified the presence of turbid seepage downstream of each dam, particularly the most recent inspections. However, this may not have been apparent due to the way seepage is currently monitored and in the past inspectors may not have been aware that they should be looking for seepage turbidity. Even though the history doesn't indicate an issue, there is never a guarantee that turbid seepage may not start in the future.

As part of this DSR, Hatch repeated the piping risk assessment for Elinor South Dam as carried out by EBA [2010], given the similar condition and relating the risks presented by South Dam considering the "High" DFCC. In addition, EBA [2010] considered one piping risk assessment for both dams, however, the seepage, conduit presence, and dam classification make the piping risk and its consequence different at the North and South Dams.

The piping failure risk assessment method used is based on Foster and Fell [2000] assessment method. This method quantifies the probability of dam failure due to potential of seepage and piping events. The Foster and Fell [2000] approach estimates the relative likelihood of dam failure by piping, P_p , by quantifying the influence of several factors that affect the likelihood of piping. The approach calculates the relative probability of several piping modes, namely:

- Piping through the embankment (E)
- Piping through the foundation (F)
- Piping of embankment into foundation (EF).

Relative probabilities are determined by assessing historical failure frequencies due to piping and seepage phenomena. The method accounts for general factors influencing the likelihood of failure. The annual likelihood of failure by piping is then calculated using the following formula:

$$P_p = w_E P_e + w_F P_f + w_{EF} P_{ef}$$

Where w_x and P_x represent the weighting factor and relative annual likelihood of failure by piping, respectively. Note that the subscript 'x' denotes a mode of failure, where 'E' represents a failure of the embankment, 'F' represents a failure of the foundation, and 'EF' represents a failure from piping of the embankment into the foundation. Refer to the paper published by Foster et al., 2000 for a more detailed explanation of the methodology.

Considering the level of information related to design and construction, despite the fact that the 2 dams are different in height, the assessment performed for the East and West Dams was the same. Furthermore, the piping risk of both dams should be addressed together due to similarities in their current consequence classifications, design concept, and construction scheme. The various assumptions utilized in the Foster and Fell [2000] analysis at the dams for the three (3) discussed failure types are presented in Table 7-17 through Table 7-19.

References for the weighting factors are provided in Figure 7-7 to Figure 7-9. Annual failure probabilities applicable to both dams are presented in Figure 7-10.

Table 7-17: Foster and Fell [2000] Coefficients for Piping through the Elinor South Embankment Dam

Factor	Factor Description	Score	Commentary
Embankment Filters	No embankment filter (for dams that usually have filters;	2	Filter criteria and compatibility unknown between upstream blanket and shell. Filter blanket existent.
Core Geological Orogen	Glacial	0.5	Source not known.
Core Soil	low plasticity silt (ML)	2.5	Source is not known. Silt type is selected conservatively.
Compaction	Rolled, modest control	1.2	Average level of compaction was assumed
Conduits	Conduit through the embankment, some poor details	2	Average construction scheme assumed; no arresting filter detail on D/S side.
Foundation Treatment - Bedrock	Irregularities in foundation or abutment, steep abutments	1.2	No detail of core foundation treatment is available.
Observations of seepage	Leakage steady, clear, or not observed	1	Seepage is observed; clean however.
Monitoring and surveillance	Irregular seepage observations, inspections weekly	1	Weekly inspection, but no leakage being measured.
Type of Embankment	Central core earth and rockfill		
Age in years	50		
Embankment type factor	34		
		7.200	
		$W_E =$	Embankment Weighting Factor
		$P_E = \frac{3.40E-05}{7.200}$	Central core earth and rockfill
		2.45E-04	
Overall Embankment Probability			

Note: USBR refers to US Bureau of Reclamation

Table 7-18: Foster and Fell [2000] Coefficients for Piping through Foundation of the Elinor South Embankment Dam

Factor	Factor Description	Score	Commentary
Foundation Filters	No foundation filter present	1	Foundation filter blanket present; however, not effective.
Foundation below cutoff	Soil	5	Not used. Foundation is granular glacial till.
Cut-off (soil foundation)	Shallow or no core trench	1.2	No core trench exists
Cut-off (rock foundation)	Not applicable	1	No cutoff constructed
Soil Geology below conduit	Glacial	0.5	not applicable
Rock Geology (below cut-off)	Not applicable	1	no cutoff
Observations of seepage	Leakage gradually increasing, clear, sinkholes, sand boils	2	Seepage is observed; clean however.
Observations of pore pressure	High pressures in foundation	1	No abnormal pore pressure occurrences in foundation; but pressure distributes in foundation.
Monitoring and surveillance	Irregular seepage observations, inspections weekly	1	Weekly inspection.
Embankment type factor	19		
$W_F = 6.000$ Foundation Weighting Factor $P_F = 1.90E-05$ Central core earth and rockfill Foundation piping probability = $1.14E-04$			

Note: General foundation properties were considered as a unit for this piping probability approximation.

Table 7-19: Foster and Fell [2000] Coefficients for Piping of Embankment into Foundation of the Elinor South Embankment Dam

Factor	Factor Description	Score	Commentary
Filters	Appears to be independent of presence-absence of embankment or foundation filters	1	no seepage from dam to foundation is expected.
Foundation cutoff trench	Shallow or no trench	0.8	No cutoff trench.
Foundation	On or partly on soil	0.5	Fully on overburden.
Erosion control measures of core foundation	None, average foundation conditions	1.2	No filter exists
Foundation Grouting	Soil foundation - not applicable	1	None.
Soil Geology Types	Glacial	2	Granular glacial till.
Rock Geology	Not applicable	1	Central core.
Core geological origin	Glacial	0.5	Galical sources were used.
Core soil type	Low placticity silt (ML)	2.5	Not much information. Assumed classification according to existing info.
Core compaction	Appears to be idependent of compaction	1	Little info.
Foundation Treatment (rock)	Irregularities in foundation or abutment, steep abutments	1.1	Foundation prep under the dam or abutments not known.
Observations of seepage	Leakage steady, clear or not monitored	1	Seepage is observed; clean however.
Monitoring and surveillance	Irregular seepage observations, inspections weekly	1	Weekly inspection happens.
Embankment type factor	4		
$W_{EF} = \frac{1.320}{4.00E-06} = 5.28E-06$ Embankment Weighting Factor Central core earth and rockfill Embankment piping into Foundation Probability =			

Factor*	General factors influencing likelihood of failure				
	Much more likely	More likely	Neutral	Less likely	Much less likely
Embankment filters $w_{E(filt)}$		No embankment filter (for dams that usually have filters; refer to text) (2)	Other dam types (1)	Embankment filter present, poor quality (0.2)	Embankment filter present, well designed, and well constructed (0.02)
Core geological origin $w_{E(geo)}$	Alluvial (1.5)	Aeolian, colluvial (1.25)	Residual, lacustrine, marine, volcanic (1.0)		Glacial (0.5)
Core soil $w_{E(cest)}$	Dispersive clays (5); low-plasticity silts (ML) (2.5); poorly graded and well-graded sands (SP, SW) (2)	Clayey and silty sands (SC, SM) (1.2)	Well-graded and poorly graded gravels (GW, GP) (1.0); high-plasticity silts (MH) (1.0)	Clayey and silty gravels (GC, GM) (0.8); low-plasticity clays (0.8)	High-plasticity clays (CH) (0.3)
Compaction $w_{E(cc)}$	No formal compaction (5)	Rolled, modest control (1.2)	Puddle, hydraulic fill (1.0)		Rolled, good control (0.5)
Conduits $w_{E(con)}$	Conduit through the embankment, many poor details (5)	Conduit through the embankment, some poor details (2)	Conduit through embankment, typical USBR practice (1.0)	Conduit through embankment, including downstream filters (0.8)	No conduit through the embankment (0.5)
Foundation treatment $w_{E(ft)}$	Untreated vertical faces or overhangs in core foundation (2)	Irregularities in foundation or abutment, steep abutments (1.2)		Careful slope modification by cutting, filling with concrete (0.9)	Careful slope modification by cutting, filling with concrete (0.9)
Observations of seepage $w_{E(obe)}$	Muddy leakage, sudden increases in leakage (up to 10)	Leakage gradually increasing, clear, sinkholes, seepage emerging on downstream slope (2)	Leakage steady, clear, or not observed (1.0)	Minor leakage (0.7)	Leakage measured none or very small (0.5)
Monitoring and surveillance $w_{E(mon)}$	Inspections annually (2)	Inspections monthly (1.2)	Irregular seepage observations, inspections weekly (1.0)	Weekly-monthly seepage monitoring, weekly inspections (0.8)	Daily monitoring of seepage, daily inspections (0.5)

Figure 7-7: Weighting Factors (Values in Parentheses) for Piping through the Embankment Mode of Failure

Factor*	General factors influencing likelihood of failure				
	Much more likely	More likely	Neutral	Less likely	Much less likely
Filters $w_{F(fin)}$		No foundation filter present when required (1.2)	No foundation filter (1.0)	Foundation filter(s) present (0.8)	
Foundation (below cutoff) $w_{F(fnd)}$	Soil foundation (5)		Rock, clay-infilled or open fractures and (or) erodible rock substance (1.0)	Better rock quality →	Rock, closed fractures and non-erodible substance (0.05)
Cutoff (soil foundation) $w_{F(cis)}$		Shallow or no cutoff trench (1.2)	Partially penetrating sheetpile wall or poorly constructed slurry trench wall (1.0)	Upstream blanket, partially penetrating, well-constructed slurry trench wall (0.8)	Partially penetrating deep cutoff trench (0.7)
Cutoff (rock foundation) $w_{F(cut)}$	Sheetpile wall, poorly constructed diaphragm wall (3)	Well-constructed diaphragm wall (1.5)	Average cutoff trench (1.0)	Well-constructed cutoff trench (0.9)	
Soil geology (below cutoff) $w_{F(sg)}$	Dispersive soils (5); volcanic ash (5)	Residual (1.2)	Aeolian, colluvial, lacustrine, marine (1.0)	Alluvial (0.9)	Glacial (0.5)
Rock geology (below cutoff) $w_{F(rg)}$	Limestone (5); dolomite (3); saline (gypsum) (5); basalt (3)	Tuff (1.5); rhyolite (2); marble (2); quartzite (2)		Sandstone, shale, siltstone, claystone, mudstone, hornfels (0.7); agglomerate, volcanic breccia (0.8)	Conglomerate (0.5); andesite, gabbro (0.5); granite, gneiss (0.2); schist, phyllite, slate (0.5)
Observations of seepage $w_{F(obs)}$	Muddy leakage, sudden increases in leakage (up to 10)	Leakage gradually increasing, clear, sink-holes, sand boils (2)	Leakage steady, clear, or not observed (1.0)	Minor leakage (0.7)	Leakage measured none or very small (0.5)
Observations of pore pressures $w_{F(opp)}$	Sudden increases in pressures (up to 10)	Gradually increasing pressures in foundation (2)	High pressures measured in foundation (1.0)		Low pore pressures in foundation (0.8)
Monitoring and surveillance $w_{F(mon)}$	Inspections annually (2)	Inspections monthly (1.2)	Irregular seepage observations, inspections weekly (1.0)	Weekly-monthly seepage monitoring, weekly inspections (0.8)	Daily monitoring of seepage, daily inspections (0.5)

Figure 7-8: Weighting Factors (Values in Parentheses) for Piping through the Foundation Mode of Failure

Factor*	General factors influencing likelihood of initiation of piping				
	Much more likely	More likely	Neutral	Less likely	Much less likely
Filters $W_{EF(FH)}$	Appears to be independent of presence-absence of embankment or foundation filters (1.0)	Appears to be independent of presence-absence of embankment or foundation filters (1.0)	Appears to be independent of presence-absence of embankment or foundation filters (1.0)	Appears to be independent of presence-absence of embankment or foundation filters (1.0)	Appears to be independent of presence-absence of embankment or foundation filters (1.0)
Foundation cutoff trench $W_{EF(COT)}$	Deep and narrow cutoff trench (1.5)		Average cutoff trench width and depth (1.0)	Shallow or no cutoff trench (0.8)	
Foundation $W_{EF(FND)}$		Founding on or partly on rock foundations (1.5)			Founding on or partly on soil foundations (0.5)
Erosion-control measures of core foundation $W_{EF(ERM)}$	No erosion-control measures, open-jointed bedrock, or open-work gravels (up to 5)	No erosion-control measures, average foundation conditions (1.2)	No erosion-control measures, good foundation conditions (1.0)	Erosion-control measures present, poor foundations (0.5)	Good to very good erosion-control measures present and good foundation (0.3-0.1)
Grouting of foundations $W_{EF(GRT)}$		No grouting on rock foundations (1.3)	Soil foundation only, not applicable (1.0)	Rock foundations grouted (0.8)	
Soil geology types $W_{EF(SGT)}$	Colluvial (5)	Glacial (2)		Residual (0.8)	Alluvial, aeolian, lacustrine, marine, volcanic (0.5)
Rock geology types $W_{EF(RGT)}$	Sandstone interbedded with shale or limestone (3); limestone, gypsum (2.5)	Dolomite, tuff, quartzite (1.5); rhyolite, basalt, marble (1.2)	Agglomerate, volcanic breccia (1.0); granite, andesite, gabbro, gneiss (1.0)	Sandstone, conglomerate (0.8); schist, phyllite, slate, hornfels (0.6)	Shale, siltstone, mudstone, claystone, (0.2)
Core geological origin $W_{EF(CGO)}$	Alluvial (1.5)	Aeolian, colluvial (1.25)	Residual, lacustrine, marine, volcanic (1.0)		Glacial (0.5)
Core soil type $W_{EF(CST)}$	Dispersive clays (5); low-plasticity silts (ML) (2.5); poorly graded and well-graded sands (SP, SW) (2)	Clayey and silty sands (SC, SM) (1.2)	Well-graded and poorly graded gravels (GW, GP) (1.0); high-plasticity silts (MH) (1.0)	Clayey and silty gravels (GC, GM) (0.8); low-plasticity clays (CL) (0.8)	High-plasticity clays (CH) (0.3)
Core compaction $W_{EF(CC)}$	Appears to be independent of compaction, all compaction types (1.0)	Appears to be independent of compaction, all compaction types (1.0)	Appears to be independent of compaction, all compaction types (1.0)	Appears to be independent of compaction, all compaction types (1.0)	Appears to be independent of compaction, all compaction types (1.0)
Foundation treatment $W_{EF(FHT)}$	Untreated vertical faces or overhangs in core foundation (1.5)	Irregularities in foundation or abutment, steep abutments (1.1)		Careful slope modification by cutting, filling with concrete (0.9)	Careful slope modification by cutting, filling with concrete (0.9)
Observations of seepage $W_{EF(OBS)}$	Muddy leakage, sudden increases in leakage (up to 10)	Leakage gradually increasing, clear, sinkholes (2)	Leakage steady, clear, or not monitored (1.0)	Minor leakage (0.7)	No or very small leakage measured (0.5)
Monitoring and surveillance $W_{EF(MON)}$	Inspections annually (2)	Inspections monthly (1.2)	Irregular seepage observations, inspections weekly (1.0)	Weekly-monthly seepage monitoring, weekly inspections (0.8)	Daily monitoring of seepage, daily inspections (0.5)

Figure 7-9: Weighting Factors (Values in Parentheses) for Accidents and Failures as a Result of Piping from the Embankment into the Foundation




Figure 7-10: Estimated Annual Probability of Failure of the Elinor Lake South Dam Using Foster and Fell [2000]

According to CDA Guidelines [CDA, 2013a], life safety risk should be consistent with values used in other hazardous industries and with the principle that risks should be made as low as reasonably practicable (ALARP). Using this principal, a better understanding of the piping risks can be obtained by plotting annual exceedance probability against the expected number of persons subjected to a Life Safety Risk. Figure 7-11 outlines the piping risk with regards to life safety risk using the DFCC of “High” an assuming a potential for Loss of Life.

The red, yellow, and green bands represent unacceptable, tolerable (as long as the risk is ALARP), and acceptable risk ranges, respectively. ALARP refers to an operating condition where all prudent measures to reduce risk have been undertaken and continuous surveillance is implemented.

In its existing condition, the total probability of piping failure at the Elinor Lake South Earthfill Dam appears to be close to unacceptable ranges. However, this potential can be reduced in a number of ways. First, as can be observed in Figure 7-11, the broadly acceptable band is highly influenced by the potential number of people.

The following activities may be undertaken to reduce the piping failure risk at the Elinor Lake South Dam:

- Provide additional training and instruction to Dam Operators to property identify, sample and respond to seepage turbidity would reduce the piping risk. Seasonal turbidity laboratory tests could then be conducted on any water samples taken (see Issue No.ES-3, All-7 in Table 13-1)

- Structural mitigation in terms of installing piping control measures such as a reverse filter blanket at the toe of dam is an alternative measure which might be considered for the Elinor South Dam which may be recommended following a geotechnical investigation and assessment. (see Issues ES-2C, ES-5, and ES-6 in Table 13-1).
- Install tick filter zone around the Outlet Conduit as per recommendation by USBR (1989).
- Conduct geotechnical investigation and assessments to further assess the internal zoning, internal stability, and filter criteria.
- Install additional instrument at dams to measure internal pore water pressure and total seepage quantity, by the installation of piezometers and weir(s), respectively.




Figure 7-11: Existing Risk Acceptability for Elinor South Earthfill Dam Considering DFCC of 10

7.4.6 Geotechnical Assessment Conclusions

Recommendations arising from the results of the Geotechnical Assessment include the following (see Issue No. ES-2C, 5, 6 in Table 13-1):

- There is a lack of site-specific geotechnical information available for Elinor Lake South Dam. The lack of information prevents a complete assessment of the geotechnical conditions. A geotechnical investigation consisting of boreholes and in-situ and laboratory

geotechnical testing should be conducted to fully characterize the materials of the embankment and foundation.

- There is history and evidence of considerable seepage quantities which may cause potential piping in the foundation. This was supported by results of the seepage analyses. Remedial works such as a filtered toe berm may be considered upon completion of the geotechnical investigation.
- The risk of piping is close to the tolerable threshold. This is supported by evidence of seepage and boiling downstream.
- The liquefaction susceptibility and post-seismic instability of the dam are likely which requires geotechnical investigation and assessment.
- Instrumentation should be installed at the dam including piezometers and weirs following a geotechnical investigation.
- Internal piping and filter criteria of the embankment dam can be assessed following a geotechnical investigation and laboratory testing.

7.5 Mechanical Assessment

The only control equipment at the site is the gate on the riparian conduit

The gate itself is a 0.457 m (18 inch) Armco heavy duty slide gate installed at the upstream/intake end of the concrete encased pipe culvert. The slide gate is connected with a 1-1/2" diameter gate rod and is manually operated via a rotating wheel assembly at the dam deck level. The gate is in generally good condition and is able to provide control for the reservoir as originally intended. This gate is not meant for and generally should not be used for flood control purposes. No further issues concerning dam safety were identified with the gate or mechanism. It should continue to be maintained in good working order and monitored for deterioration and leakage.

8. Public Safety and Security

In 2011, the CDA published guidelines for Public Safety Around Dams [CDA, 2011] and the 2013 revision of the CDA Dam Safety Guidelines [CDA, 2013a] outlines the requirements to address Public Safety and Security in Section 5.4.8. However, public safety and security are not explicitly addressed under the BC Dam Safety Regulation [B.C. Reg 44/2016]. In general, managing public safety and security around dams are important for the dam owner in order to ensure that the presence and normal operation of their structure does not pose an unacceptable risk to the public and to mitigate potential liability should a member of the public become injured at their structure.

8.1 Site Observations

Elinor South Dam is accessible by either 4x4 vehicles, hiking, snowmobile, motorbikes or off-road recreational vehicles (ATV), and vehicle access is made available via the Elinor Lake Forestry Service Road. ATV trails were generally present in the area, indicating the presence of the public around this structure. While this is not an immediate concern, it indicates the type of access the public has to the site and the potential for safety incidents to occur. Indicators of public presence include shotgun casings and garbage.

Currently, there is a sign including contact information for dam safety concerns, including contacts for an emergency, a locked outlet gate preventing public operation of the gate, and a log boom in front of the spillway restricting access to the spillway directly from the lake.

8.2 Public Safety Management Plan Audit

RDOS does not currently have a comprehensive public safety management plan in place for Elinor South Dam, however, a “Risk Control Survey” has recently been completed by Precise Services in 2019 with the intent of identifying exposures to liability and to assist the risk management and public works staff in managing those exposures. As such, some of the types of control measures recommended within this document are similar to those expected as part of a formal public safety around dams management plan. These include fencing, signage, barriers at the low flow outlet structure, informative signage, warning signage and gates.

A summary of the findings and recommendations of the report is provided below for each component along with additional comments as applicable. All outstanding recommendations in the Risk Control Survey should be implemented.

8.2.1 *General*

The Risk Control Survey recommends the addition of additional large boulders that cannot be moved by truck winches or off-road vehicles to discourage off-road vehicles from driving around on the dam face, as well as signage to provide information about the dams, water flow, the use of the water in the event of emergency, off-road vehicle restrictions and why, a requirement to pack out what you pack in, ask the public to observe, record and report if they see others vandalizing any aspect of the dam infrastructure.

No signage was present on the dam itself to warn of steep slopes and fall hazards.

8.2.2 Riparian Conduit Structure

The Risk Control Survey recommends barriers at the low flow outlet structure as fall protection.

During the site visit it was noted that the riparian conduit wheel is locked and therefore restricted from public operation, however there is no signage warning the public of danger.

No warning signs or buoys are present around the riparian conduit inlet to indicate the presence of a submerged inlet. The inlet is deep enough below FSL that it is unlikely a vortex would form that could affect boaters at the water surface. However, swimmers or other users should be alerted to the presence of potentially dangerous currents in this area of the dam. Although the risk control survey made some good recommendations, it is recommended that a brief supplemental public safety risk analysis and assessment in accordance with CDA Guidelines be undertaken to determine the need and form of signage and safety buoys that may be required in this area.

8.2.3 Spillway

The Risk Control Survey generally recommends signage, as indicated above, which could pertain to this area.

There is a debris boom at the approach to the spillway inlet. No warning signs were observed in the spillway approach channel to warn boaters or swimmers to stay away from the spillway. No warning signs were present along the approach channel for pedestrian or road access.

It is recommended that a brief supplemental public safety risk analysis and assessment in accordance with CDA Guidelines be undertaken to determine the need and form of signage and safety control measures that may be required in this area.

8.3 Recommendations

We recommend that all outstanding recommendations in the Risk Control Survey be implemented with a high priority. A supplemental public safety risk analysis and assessment should be considered in the future to align with CDA Guidelines [CDA, 2011]. This exercise would ensure that all hazards have been considered and covered off and serve as formal documentation of public safety improvement and reduction of liability for RDOS.

9. Dam Safety Management

The CDA Dam Safety Guidelines state that “The owner is responsible for the safe management of a dam. Dam safety management takes place within the context of public safety reassuring the public and stakeholders that risks to people, property, and the environment are being properly addressed.” The Guidelines also state that “A dam safety management system, incorporating policies, responsibilities, plans and procedures, documentation, training, and review and correction of deficiencies and non-conformances, shall be in place.” Dam owners can demonstrate a commitment to diligent safety management through the implementation of a formal Dam Safety Management System.

The CDA Dam Safety Guidelines note that the effectiveness of the dam safety management system should be assessed during the course of a DSR. Key elements of the management system are policy development, planning, implementation of procedures, checking, corrective action, and reporting. Indications of effectiveness include the following:

- Roles, responsibilities, and authorities are clearly assigned
- Key activities are clearly assigned
- Personnel understand their roles and responsibilities and training is administered
- Operation, maintenance, and surveillance activities are carried out and documented
- Safety measures recommended in previous Dam Safety Review reports have been carried out
- Other supporting documentation (as-built drawings, design calculations, engineering studies, monitoring data, licenses) are readily available.

The RDOS has a dam safety strategy that is in compliance with the B.C. Dam Safety Regulation [B.C. Reg 44/2016] under the Water Sustainability Act, but no formal Dam Safety Management policy document was provided. RDOS has an OMS Manual with documented OMS procedures or activities, and a DEP specific to the dam. Regular surveillance and maintenance activities are conducted. Dam safety training is understood to be completed on the job; although documentation of such is not available.

Recommendations from the previous Dam Safety Review by EBA in 2010 have been partially implemented to date. A number of Dam Safety Concerns are being acted on, as is the case with the boil scenario at Naramata Dam that emerged just prior to this DSR inspection.

Pertinent records including drawings, consultant reports and some monitoring records are readily available.

Based on the above, it is evident that RDOS has implemented a number of the elements of an effective Dam Safety Management System with the main shortfalls found in proper documentation of their activities rather than performance of the requirements. RDOS should

continue to improve operation, maintenance, and surveillance protocols, improve DEPs as required, and conduct independent dam safety reviews and audits.

RDOS should ensure that its existing dam safety activities are continued in the context of a Dam Safety Management System which provides an overall framework for safety activities, decisions, and supporting processes. This is particularly important to maintain continuity in the event of internal reorganization or changing responsibilities for dam safety. The system should include implementation of the following.

- Dam Safety Policy, defining ultimate accountability and authority for implementation
- Documented annual reports to management on the state of dam safety activities
- Keeping of employee training records, inspection records, and DEP testing and training records
- Public Safety Management Plan.

An overview of the elements of an owner's Dam Safety Management System as described in the CDA Dam Safety Guidelines is shown in Figure 9-1. Additional detail is provided in the following sections.




Figure 9-1: Overview of a Dam Safety Management System

9.1 Policy Development

The owner should have a Dam Safety Policy that clearly demonstrates commitment to safety management throughout the complete life cycle of the dam. The Policy should define the following:

- The level of safety that is to be provided, and the safety criteria to be used. Applicable regulations must be met, and industry practice and due diligence must be taken into account.

- Ultimate accountability and authority in the organization for ensuring that the policy is implemented. To ensure that safety objectives are not considered secondary to other objectives, accountability for dam safety should be placed at the highest level of management.
- The delegation of responsibility and authority for all dam safety activities. Key individual positions accountable for dam safety, operation, surveillance and maintenance should be identified, along with their responsibilities for internal and external reporting.
- The process for making decisions related to dam safety. Critical safety decisions with significant societal or financial implications should be made or approved at the highest level.

We recommend that every dam owner develop a comprehensive policy regarding dam safety so that in an emergency situation the dam managers and operators are empowered to make critical decisions and have clear guidance in making these decisions. This type of policy has been shown to be instrumental in preventing dam safety emergencies from progressing into disasters in numerous situations.

9.2 Planning

Planning involves identifying the items in a dam safety work program, assigning responsibilities for carrying out each item, and ensuring resources are adequate to carry out the work. It is often useful to consider three levels of planning: the strategic or long-range plan (5 to 10 years); the management plan (annual); and operational plans specific to an individual project or task. RDOS currently has a planning process in place that should be more formally documented within their dam safety program.

9.3 Implementation

Ongoing activities associated with dam safety management include operation, maintenance and surveillance, and emergency preparedness. RDOS's regular operations, maintenance and surveillance activities are generally carried out in a structured manner. The results of the current project formalize their DEP and OMS manuals. These should continue to be improved and updated to provide better records of what is planned and what is completed.

9.4 Checking and Reviewing

The Dam Safety Management System should include processes for checking and reviewing dam performance and the management system itself.

Inspections, monitoring and assessment of data, testing of equipment, and emergency exercises are processes to check and review the condition and performance of the dams and their components. Dam Safety Reviews should be performed periodically to provide independent assurance that current safety requirements are met and to make recommendations for improvement.

After any significant dam safety incident, the owner should carry out an investigation to determine root causes, minimize potential for such incidents to happen again, and ensure that lessons learned are incorporated into the system and communicated to staff.

RDOS undertakes periodic reviews of their monitoring and surveillance data. These should be further formalized and documenting as part of their dam safety management program. DSRs are being conducted on a regular basis and should continue to be performed on the required schedule.

9.5 Corrective Actions

The Dam Safety Management System should include a process for timely follow-up and correction whenever safety deficiencies or non-conformance with standards, policies or procedures are identified. This includes prioritizing corrective actions. Prioritizing should take into account the consequences of potential dam failure, the magnitude and significance of the deficiency or issue in question, a risk assessment of the deficiency, applicable regulations and laws, and financial resources.

A strategy for implementing corrective actions and improvements should be implemented and should include priority (the order in which actions should be taken), urgency (how soon the actions should be taken), and progressive improvement (whether the actions can be implemented in stages).

The results of this DSR provide a starting point for dam safety issues tracking and mitigation. This should continue to be formalized and documented in the future.

9.6 Reporting

As a minimum, senior management should be updated annually on the status of the dam safety program. The update should cover:

- Results of the various reviews
- Outstanding issues and deficiencies
- Incidents
- Corrective actions
- Adequacy of policies and procedures (or need for change)
- Program objectives
- Adequacy of resources.

This is one area where RDOS can improve to better document their activities and issues tracking, providing better clarity and understanding for themselves, the BC Dam Safety office and for future DSRs.

9.7 Supporting Processes

9.7.1 *Training and Qualification*

Supporting processes include adequate training of all individuals with responsibilities for dam safety activities. Training records should be maintained. Training can take the form of internal training, formal courses (held online by bodies such as CDA, USSD, ASDSO, USBR etc.), participation in the BC Dam Safety Office's seminars and self-study of dam safety publications and journals.

9.7.2 *Program Communication*

It is of utmost importance that the dam safety policy and management commitment be clearly communicated to staff involved in dam safety activities. Dam safety awareness and a culture of continuous improvement should be supported.

Contact with stakeholders (including emergency responders and civic authorities) is necessary during the development, maintenance and testing of plans involving public safety and emergency preparedness.

Once the DEPs are reviewed and accepted a program of regular updates and testing should be implemented to assure the currency of the documents into the future.

9.7.3 *Record Keeping and Management*

Documentation should be kept up to date so there is a permanent record of (i) the design, construction, operation and performance of the dam; and (ii) the management of its safety. Such documents typically include, but are not limited to:

- An inventory of dams and appurtenant structures in the system
- Permits and licenses
- Design records
- Geotechnical investigation records
- As-built drawings
- Construction completion reports
- Photo and video records of construction activities at various stages
- Instrumentation readings and other technical data
- Inspection and test reports
- Dam Safety Review reports
- Operation and maintenance records
- Closure plans, if any
- Records of dam safety incidents, lessons learned, and follow-up actions

- Records of staff training
- Records of flow control equipment tests
- Records of emergency preparedness tests and follow up actions.

9.8 Recommendations

Based on the above, it is evident that RDOS has implemented a number of the elements of an effective Dam Safety Management System. RDOS should continue to improve operation, maintenance, and surveillance protocols, improve DEPs as required, and conduct independent dam safety reviews and audits. Hatch recommends the following Dam Safety Management actions:

- The RDOS should adopt a formal policy statement on Dam Safety for their program to satisfy the CDA Dam Safety Guidelines. This will demonstrate a commitment to the regulation and provides a reason to perform necessary works. (See Issue No. All-4 in Table 13-1).
- RDOS staff responsible for the DEP should regularly attend BC Dam Safety Dam Management seminars on dam safety and inspections (understood to be provided annually in most areas of BC, including Penticton). Records of attendance at these inspection workshops should be documented along with information on any additional training completed. This could include review of material provided on BC Dam Safety website. (See Issue No. All-7 in Table 13-1).
- Provide documented training to staff in emergency procedures, and carry out and document regular exercises to test the emergency procedures. Follow additional recommendations in proposed new Dam Emergency Plan (DEP) procedure. (See Issue No. All-8 in Table 13-1).

10. Operations, Maintenance and Surveillance

Elinor South Dam has a DFCC of “High”. Under the B.C. Dam Safety Regulation [B.C. Reg 44/2016] and the Water Sustainability Act, a dam under such DFCC requires additional general safety requirements. This includes the preparation of an Operation, Maintenance and Surveillance (OMS) manual and a Dam Emergency Plan (DEP) (see Section 1). The OMS manual must be accepted by the Dam Safety Officer. The CDA Dam Safety Guidelines [CDA, 2013a] recommend that an OMS manual be prepared for each dam project. It should include operating procedures for normal, unusual and emergency conditions. Maintenance procedures should ensure that the dam remains in a safe and operational condition. The surveillance portion of the manual should allow for early identification of issues and allow for timely mitigation of conditions that could affect dam safety.

Hatch has reviewed the combined Operation, Maintenance and Surveillance Plan Emergency Preparedness Plan (OMS EPP) manual prepared by RDOS dated May 2017 [RDOS, 2017], which includes Elinor South Lake Reservoir and Dam. As part of this project Hatch undertook the separation and update of the OMS and DEP into standalone documents as required by the Dam Safety Regulation. These documents provided some areas that RDOS is required to update and submit to the Dam Safety Office. Into the future, once approved, both of these documents should be reviewed and updated at least annually. Formally, they should be reviewed, revised if necessary, and the revision should be submitted to the DSO every 10 years.

Findings relating to the operation, maintenance, and surveillance of Elinor South Dam are outlined in the following sections.

10.1 Operation

10.1.1 *Normal Operations*

The OMS manual produced as part of this project provides adequate information of monitoring and operation of Elinor South Dam during normal flow conditions. This includes inflow forecasting, the filling schedule and release procedures. RDOS may compare the documented Snow Survey Sites with previous years’ records on file to predict the potential runoff to the storage reservoirs or at the diversion intake. As part of the reservoir filling schedule, the upstream Chute Creek Diversion can be operated to allow inflows to Elinor Lake followed by Naramata Lake. Once Elinor Dam is filled to 3 ft below its full pool elevation and Naramata Dam is filled to 2 ft below its full pool elevation, the Chute Creek Diversion gate is manually closed. The full supply level/ full pool level of the reservoir is managed by inflow into the spillway channel once water levels exceed the FSL of 1271.95 m which is the crest elevation of the spillway weir. Big Meadow Dam, located upstream of the Chute Creek Diversion, is opened by the end of July. If the water level at Naramata Dam has been drawn down by outlet operations, water can again be diverted through the system to Elinor Lake and

Naramata Lake. During the summer months the goal is to have a stable drawdown of all of the dams through closely monitored levels and adjustments.

10.1.2 Flood Operations

As the spillway includes a weir with no control gates, there are generally no flood operations associated with the Elinor South Spillway.

A marking system along the gate hoist stem is available to measure water levels. Regular recording of water levels is noted by RDOS in their Routine Dam Inspection Reports. These are recorded weekly as per regulation during the high-water period. As part of the reservoir filling schedule, the upstream Chute Creek Diversion gate would be closed prior to reaching the FSL. Documentation on how and when this system should be operated is included in the OMS manual.

During times of extreme reservoir inflows, the process for issuing inflow forecasts by comparing the documented Snow Survey Sites with previous years' records on file to predict the potential runoff to the storage reservoirs or at the diversion intake should be outlined. The OMS manual should provide a table with these comparisons, as well as the rating curves for the structures to facilitate calculation of outflows. A rating curve was added to the OMS Manual during this study. Any recommended drawdown in anticipation of large spring runoff events should also be documented.

10.1.3 Emergency Operations

The manual should indicate the policy to be followed should an unusual condition develop at Elinor South Dam. The OMS has been updated to refer to the Dam Emergency Plan (DEP) in this scenario. The DEP has been updated using the BC Dam Safety "Guide & Template for Preparing a Dam Emergency Plan (DEP) in British Columbia", which fully defines the processes and responsibilities related to emergency management.

The DEP indicates the operating rules to be followed if an unusual condition develops at Elinor South Dam. The CDA Guidelines [2013a], recommend having flood operating rules that are specific enough that Dam Operators can easily understand and follow them. Additional detail in the Dam Emergency Plan directing Dam Operators on how to identify an emergency condition would be helpful to be included (see Issue No. All-5 in Table 13-1).

Given the steepness of the drainage basin and speed of a runoff even it is unlikely that additional pumping, syphon or drawdown capacity would be useful in managing a single event. However, in the case of a series of rainfall events it may be useful to have the capacity available to help drawdown between events. In addition, emergency drawdown may be required in the case of a potential failure event (i.e., rapid increase in turbid seepage, structural movement of either of the dams or after an earthquake event).

For the Naramata Dam, it has been recommended that RDOS have on hand one (1) or more high volume pumps or a portable syphon in the case that high water levels are observed and assistance in drawdown is required. This has been specifically called out as the reservoir has

recently required rapid drawdown due to the boil issue. These units could be used at Elinor Lake South if a need for emergency drawdown ever presents itself (as in after a seismic event). It is recommended that an understanding of the rate of drawdown that can be achieved through this method should be evaluated for operations planning (see Issue No. All-5 in Table 13-1).

10.2 Maintenance

As stated in the CDA Guidelines [CDA, 2013a], the maintenance of equipment and systems is pertinent to ensure safe operations and to upkeep the integrity of the dam. In the BC Dam Safety Regulation [B.C. Reg 44/2016], a “High” DFCC dam is expected to have site surveillance conducted on a weekly basis and a formal inspection on an annual basis. Ongoing maintenance checks have been conducted by RDOS staff on a regular basis with annual dam safety inspections and weekly site inspections. The frequency of inspections held since the previous Dam Safety Review is currently adequate and should be continued.

The OMS Manual includes a general discussion on maintenance, followed by maintenance instructions and required frequency for the earthfill dam, outlet works, spillway channel, instrumentation and signage.

10.3 Surveillance

Under Section 3.4.4 of the CDA Guidelines [CDA, 2013a], information related to flow control system operations should be identified and documented. In the BC Dam Safety Regulation, it states that a dam owner must install necessary instruments and maintain or replace the instrumentation to adequately monitor the dam and the surrounding area.

The OMS Manual including Surveillance and Inspection, includes sections and discussion on: Inspection equipment to bring to the inspection and procedure for recordings, Inspection frequencies for components, Routine Surveillance procedures including a Dam Inspection Checklist to be used in conjunction with the provincial Inspection and Maintenance of Dams Manual Appendix F, though a list of key points from this manual are included in the OMS as well; Important Site Specific surveillance conditions; deficiencies; instrumentation; and instruction on when to notify higher authorities.

A review of the annual dam inspection reports shows that in general they conform to the requirements of the BC Dam Safety Regulation. The most recent Formal Annual Inspection forms follow the form provided by the BC Dam Safety Office in their Annual Formal Inspection Form. However, the Routine Dam Inspection Report could be improved by more closely following the form provided by BC Dam Safety Office in their Site Surveillance Form, used for weekly inspections (included in the updated OMS manual). This form can be tailored to the dam itself to include items that are currently documented on the RDOS form and the basic information reused from year to year but in general it provides a more detailed assessment of the dam condition and may reduce the potential of missing an emerging issue.

In addition, should a new geotechnical investigation be undertaken and additional piezometers installed, these should be monitored on a regular basis to detect changes and trends.

10.4 Recommendations

Hatch recommends the following OMS actions:

- The Routine Dam Inspection report format should be improved by incorporating aspects of the BC Dam Safety Office's Site Surveillance Form (included in the updated OMS manual). (See Issue No. All-3 in Table 13-1).
- Install new instrumentation including piezometers and reinstate/install weirs downstream of the dam along the channels. Piezometer installation will be carried out as part of geotechnical investigation. The instrumentation monitoring shall include continuous records, plotting, and interpretation of piezometer data and seepage flow quantities against reservoir elevation. (See Issue No. ES-2c and ES-2d in Table 13-1).
- Logs should be kept to show that a review of the OMS is being completed annually, including the documentation of annual training refresher on the OMS Manual and DEP.

11. Dam Emergency Plan

In British Columbia as per Sections 9 and 33 of the Dam Safety Regulation, Water Sustainability Act [B.C. Reg 40/2016], an owner of a dam that has a consequence of failure classification of SIGNIFICANT, HIGH, VERY HIGH or EXTREME must prepare a Dam Emergency Plan (DEP) that includes

- A record describing actions to be taken by the owner if there is an emergency at the dam
- A record containing information for the use of the local emergency authorities for the dam for the purpose of preparing local emergency plans under the Emergency Program Act.

The new regulation still requires dam owners to prepare an emergency plan, but it is now called a Dam Emergency Plan (DEP) and includes some differences including what they contain, what must be done with them, and the date by which they must be prepared and submitted for acceptance by the Dam Safety Officer (DSO). The OMS EPP manual [RDOS, 2017] contains an EPP (Emergency Preparedness Plan) section that generally complies with both the BC Dam Safety Regulation and the CDA guidelines. However, it has previously been noted that some improvements can be made to more fully define the processes and responsibilities related to emergency management. A Guide & Template for Preparing a Dam Emergency Plan (DEP) in British Columbia has been developed to assist dam owners in preparing their DEP. Information in the existing EPP has been brought into this template as part of this study, and any additional relevant information that has come to light during this DSR has been added. This standalone document should be submitted to the DSO for acceptance.

The EPP component of the OMS EPP manual [RDOS, 2017] contains the following sections, which have been brought into the DEP template as appropriate:

- Introduction
- Responsibility
- Emergency Reporting
- Assessment and Categorization of the Emergency
- Emergency Response
- Emergency Materials.

Appendices of information include RDOS Emergency Contacts with a list of contractors and material location, a map of possible affected areas (which can be updated following the “Naramata Dam Breach Assessment and Inundation Mapping” 2020 report), Inundation Properties and Infrastructure Data.

The inundation maps included in the DEP have been updated as part of this study.

11.1 Recommendations

Hatch recommends the following DEP actions:

- Provide documented training to staff in emergency procedures, and carry out and document regular exercises to test the emergency procedures. Follow additional recommendations in proposed new Dam Emergency Plan (DEP) procedure.
- It is recommended that an understanding of the rate of drawdown that can be achieved should be evaluated for operations planning and documented in the DEP. Under the CDA Guidelines [2013a], it is recommended to provide information on staffing requirements and the time required to complete system operations so that an appropriate response can be initiated during an emergency (see Issue No. All-5 in Table 13-1).
- It is recommended that the RDOS emergency call alert system, CivicReady be setup to allow for public signup in order to receive external text message notifications during an emergency, if possible. The current Emergency Response and Notification does meet the recommendations in the BC Dam Safety Regulation [B.C. Reg 44/2016] CDA Guidelines [CDA, 2013a].
- Use results of the Dam Break analysis to form the Emergency Evacuation Plan.
- Consider using results of Dam Break analysis to prioritize contact list of downstream population to notify in an emergency.

12. Dam Safety Expectations and Deficiencies

12.1 Dam Safety Review Assurance Statement

A Dam Safety Review Assurance Statement was completed by Hatch Ltd. to verify that the DSR was completed in accordance with the APEGBC Guidelines and is included in **Appendix E**.

The definitions of Deficiencies and Non-Conformances used during this DSR are listed in Table 12-1.

**Table 12-1: Definition of Deficiencies and Non- Conformances
 [FLNRO, 2015]**

Deficiencies	
An	Actual performance deficiencies under normal loading conditions.
Au	Actual performance deficiencies under unusual loading conditions.
Pn	Potential performance deficiencies under normal loading conditions, expected to be confirmed as actual deficiencies by means of analysis in a dam performance investigation.
Pu	Potential performance deficiencies under unusual loading conditions, expected to be confirmed as actual deficiencies by means of analysis in a dam performance investigation.
Pq	Potential deficiencies under normal or unusual loading conditions, that would lead to dam safety improvements if it could not be readily (quickly) demonstrated that such procedures for activities required for normal or unusual load conditions.
Pd	Potential performance deficiencies under normal or unusual loading conditions, in the following senses: The "Dam" meets minimum performance goals, but additional safety benefits are desirable, practicable and affordable, or, the uncertainties around the concern are such that it is extremely difficult if not impossible to demonstrate that safety improvements are neither required nor desirable.
Non-Conformances	
NCo	Non-Conformance Operational: Established operational procedures, systems and instructions are not being followed, or, they are inadequate or inappropriate and should be revised.
NCm	Non-Conformance Maintenance: Established maintenance procedures, systems and instructions are not being followed, or, they are inadequate or inappropriate and should be revised.
NCs	Non-Conformance Surveillance: Established surveillance procedures, systems and instructions are not being followed, or, they are inadequate or inappropriate and should be revised.
NCi	Non-Conformance Information: There is a deficiency in information required to determine if an actual or potential performance deficiency exists. There is not enough information to determine if an Actual or Potential Deficiency exists.
NCp	Non-Conformance Procedures: Other established procedures, systems and instructions are not being followed, or, they are inadequate or inappropriate and should be revised.

Identified issues have been categorized as non-conformance, actual deficiency or potential deficiency, as outlined in the Dam Safety Expectations table, Table 12-2.

Table 12-2: Dam Safety Expectations

	DAM SAFETY EXPECTATIONS	Yes	N/A	No	Deficiencies		Non-conformances	Comments
					Actual	Potential		
1	Dam Safety Analysis							
1.1	Records relevant to dam safety are available including design documents, historical instrument readings, inspection and testing reports, operational records and investigation results.			X			NCi	There is insufficient official as-built information, and limited construction records and drawings of the dam were available during this review. Official topographic survey of the dam was carried out in 2012. Likely no further information will be found through document search. No past post-construction geotechnical investigation and instrument installation were carried out at the dam. Additional geotechnical investigations are needed to fill in knowledge gaps.
1.2	Hazards external and internal to the dam have been defined	X						Yes, as part of the current DSR.
1.3	The potential failure modes for the dam and the initial conditions downstream from the dam have been identified	X						Potential failure modes for the dam have been identified as part of this study. A full inundation study and downstream consequence classification has been undertaken as part of this study.
1.4	Inundation study adequate to determine consequence classification. Flood and "sunny day" scenarios assessed.	X						A full inundation study and downstream consequence classification has been undertaken as part of this study including the assessment of 5 potential inflow design floods and sunny day scenarios.
1.5	The Dam is classified appropriately in terms of the consequences of failure including life, environmental, cultural and third-party economic losses.	X						Has been assessed as part of this study.
1.6	All components of the water barrier (including retaining walls, saddle dams, spillways, road embankments) are included in the dam safety management process.	X						Yes, all water barrier system components were considered including the dam and its foundations.
1.7	The EDGM selected reflects current seismic understanding	X						Yes, this was assessed as part of the current study. No site-specific seismic hazard assessment is deemed necessary.
1.8	The IDF is based on appropriate hydrological analyses	X						Yes, this has been assessed as part of this study.
1.9	The dam is safely capable of passing flows as required for all applicable loading conditions (normal, winter, earthquake, flood)	X						Low level outlet performs as expected. Reservoir is empty or near-empty in winter condition (N/A). The dam is capable of passing its Inflow Design Flood without overtopping. A seismic event is not expected to adversely affect the slopes, spillway channel and path; any distress can be readily fixed.
1.10	The dam has adequate freeboard for all applicable operating conditions (normal, winter, earthquake, flood)			X			NCi	Topographical survey of embankment demonstrates some loss of freeboard. Freeboard analysis including wind/wave effects for normal and IDF conditions has been analyzed as part of this DSR and is adequate. Dam resistance to liquefaction and post-seismic stability is not known and requires investigation and assessment.
1.11	The dam safety analyses (stability & hydrological) use current information and standards of practice			X			NCi	Yes, as presented in the DSR report, stability assessments are done based on best practice. Information related to the embankment and its foundation shear strength parameters, compaction, pore water pressure, and internal stability is limited. A geotechnical investigation and subsequent assessment are needed for the dam assessment. Filter and internal stability assessment of embankment is also needed.
1.12	The approach and exit channels of discharge facilities are adequately protected against erosion and free of any obstructions and hazards that could adversely affect the discharge capacity of the facilities	X						Log boom has been installed upstream of spillway. Continue maintenance and assess the condition of masonry rock along the spillway when the spillway is not in use.

	DAM SAFETY EXPECTATIONS	Yes	N/A	No	Deficiencies		Non-conformances	Comments
					Actual	Potential		
1.13	The dams, abutments and foundations are not subject to unacceptable deformation or overstressing	X						The dam, abutments, and foundation are performing well corresponding to loads, deformation and stress. Slopes are relatively shallow and no sign of distress was observed and expected.
1.14	Adequate filter and drainage facilities are provided to intercept and control the maximum anticipated seepage and to prevent internal erosion			X		Pn, Pu	NCi	The dam was designed without a filter blanket or toe. Seepage at the toe of the embankment has been observed in the past. Exit gradients are high. The design of a toe berm incorporating a filter should be investigated after conducting a geotechnical investigation, testing, assessment, and piezometer installation.
1.15	Hydraulic gradients in the dams, abutments, foundations and along embedded structures are sufficiently low to prevent piping and instability			X		Pn, Pu	NCi	Hydraulic exit gradients at the toe of the dam are high. Conduct a geotechnical investigation and install instrumentation. Analysis should be re-conducted based on parameters derived from an intrusive investigation at the site so that the nature and dam zones engineering parameters can be better defined. Should the re-analysis conclude that the toe has marginal stability, the design of a toe berm incorporating a filter should be investigated.
1.16	Slopes of the embankments have adequate protection against erosion, seepage, traffic, frost and burrowing animals			X			NCm	Dam exhibits erosion from vehicle traffic. No upstream riprap exists on the dam slope. No significant erosion was reported in the past due to wave and surge effects. Seepage on the downstream slope has been observed and reported in the past.
1.17	Stability of reservoir slopes are evaluated under all conditions and any unacceptable risk to public safety, the dam or its appurtenant structures is identified.	X						Reservoir sides slopes are considered suitable therefore present no perceived risk. No sign of distress or concern were raised in the past as well.
1.18	The need for reservoir evacuation or emergency drawdown capability as a dam safety risk control measure has been assessed.			X			NCo	Need for emergency drawdown should be assessed.
2	Operation, Maintenance and Surveillance							
2.1	Responsibilities and authorities are clearly delegated within the organization for all dam safety activities	X						Should include a table with positions and associated names describing roles and responsibilities. Added as part of this project.
2.2	Requirements for the safe operation, maintenance and surveillance of the dam are documented with sufficient information in accordance with the impacts of operation and the consequences of dam failure	X						
2.3	The OMS Manual is reviewed and updated periodically when major changes to the structure, flow control equipment, operating conditions or company organizational structure and responsibilities have occurred.	X						Assumed. The OMS EPP was last reviewed in 2017 where updates were made to the filling and release procedures, among others. OMS and DEP have been updated as part of the current study.
2.4	Documented operating procedures for the dam and flow control equipment under normal, unusual and emergency conditions exist, are consistent with the OMS Manual and are followed	X						
	Operation							
2.5	Critical discharge facilities are able to operate under all expected conditions.							
a.	Flow control equipment are tested and are capable of operating as required.	X						Flow control equipment is routinely/seasonally operated which satisfies annual testing of mechanical components of the dam.
b.	Normal and standby power sources, as well as local and remote controls, are tested.		X					N/A
c.	Testing is on a defined schedule and test results are documented and reviewed.	X						Flow control equipment is routinely/seasonally operated which satisfies annual testing of mechanical components of the dam.
d.	Management of debris and ice is carried out to ensure operability of discharge facilities	X						Debris boom is present at spillway. It is cleaned as needed.

	DAM SAFETY EXPECTATIONS	Yes	N/A	No	Deficiencies		Non-conformances	Comments
					Actual	Potential		
2.6	Operating procedures take into account:							
a.	Outflow from upstream dams	X						
b.	Reservoir levels and rates of drawdown	X						
c.	Reservoir control and discharge during an emergency	X						
d.	Reliable flood forecasting information	X						
e.	Operator safety	X						
	Maintenance							
2.7	The particular maintenance needs of critical components or subsystems, such as flow control systems, power supply, backup power, civil structures, drainage, public safety and security measures and communications and other infrastructure have been identified	X						
2.8	Maintenance procedures are documented and followed to ensure that the dam remains in a safe and operational condition	X						
2.9	Maintenance activities are prioritized and carried out with due consideration to the consequences of failure, public safety and security			X			NCm	Clear evidence that maintenance activities are being carried out in the records. Low dam crest should be compensated to restore crest.
	Surveillance							
2.10	Documented surveillance procedures for the dam and reservoir are followed to provide early identification and to allow for timely mitigation of conditions that might affect dam safety			X			NCs	Currently there is not much instrumentation or procedures for flow monitoring to flag the seepage quantity increase downstream of the dam.
2.11	The surveillance program provides regular monitoring of dam performance, as follows:							
a.	Actual and expected performance are compared to identify deviations			X			NCs	No instrumentation installed in dam to monitor performance. Installation of piezometers in the embankment and abutment are recommended, and instrumentation to monitor toe seepage.
b.	Analysis of changes in performance, deviation from expected performance or the development of hazardous conditions			X			NCs	No instrumentation installed in dam to monitor performance. Installation of piezometers in the embankment and abutment are recommended, and monitoring of toe seepage.
c.	Reservoir operations are confirmed to be in compliance with dam safety requirements	X						The dam does not require operation. The dam spillway is a free overflow weir.
d.	Confirmation that adequate maintenance is being carried out			X			NCs	Maintenance requirements documented in weekly inspections and some maintenance documentation was provided within these forms as well. Regular recording of maintenance completion would further support that this is being completed.
2.12	The surveillance program has adequate quality assurance to maintain the integrity of data, inspection information, dam safety recommendations, training and response to unusual conditions			X			NCp	Weekly inspections are adequate. Recommend using the BC Dam Safety "Site Surveillance" checklist customized to this dam for weekly inspections to make sure nothing is missed.
2.13	The frequency of inspection and monitoring activities reflects the consequences of failure, dam condition and past performance, rapidity of development of potential failure modes, access constraints due to weather or the season, regulatory requirements and security needs.	X						Dams inspected weekly, weather permitting and documented.
2.14	Special inspections are undertaken following unusual events (if no unusual events then acknowledge that requirement to do so is documented in OMS).	X						

	DAM SAFETY EXPECTATIONS	Yes	N/A	No	Deficiencies		Non-conformances	Comments
					Actual	Potential		
2.15	Training is provided so that inspectors understand the importance of their role, the value of good documentation, and the means to carry out their responsibilities effectively.			X			NCs	No available documentation provided to show if regular dam safety training is provided to the inspector(s). As a minimum RDOS staff responsible for the DEP should regularly attend BC Dam Safety Dam Management seminars on dam safety and inspections (understood to be provided annually in most areas of BC, including Penticton). Records of attendance at these inspection workshops should be documented along with information on any additional training completed. This could include review of material provided on BC Dam Safety website.
2.16	Qualifications and training records of all individuals with responsibilities for dam safety activities are available and maintained			X			NCs	No available documentation provided to show if regular dam safety training is provided to the inspector(s).
2.17	Procedures document how often instruments are read and by whom, where the instrument readings will be stored, how they will be processed, how they will be analyzed, what threshold values or limits are acceptable for triggering follow-up actions, what the follow-up actions should be and what instrument maintenance and calibration are necessary.			X			NCs	No instrumentation installed in dam to monitor performance. Installation of piezometers in the embankment and abutment are recommended, and instrumentation (weirs) to monitor toe seepage.
3 Emergency Preparedness								
3.1	An emergency management process is in place for the dam including emergency response procedures and emergency preparedness plans with a level of detail that is commensurate with the consequences of failure.	X						The existing EPP has been incorporated into the BC Dam Safety DEP template. Dam Breach inundation maps and emergency contact information from downstream landowners has been updated in 2017.
3.2	The emergency response procedures outline the steps that the operations staff is to follow in the event of an emergency at the dam.	X						
3.3	Documentation clearly states, in order of priority, the key roles and responsibilities, as well as the required notifications and contact information.	X						There is an Appendix with an Emergency Contact List for both RDOS and for those located in the potential inundation zone (updated 2017). This information has not been made available to review for privacy purposes, but it has been stated that it exists. With new information on inundation zone, the contact list for downstream inundation could be prioritized.
3.4	The emergency response procedures cover the full range of flood management planning, normal operating procedures and surveillance procedures	X						
3.5	The emergency management process ensures that effective emergency preparedness procedures are in place for use by external response agencies with responsibilities for public safety within the floodplain.	X						DEP has been prepared. Consider using results of Dam Break analysis to form the Emergency evacuation Plan.
3.6	Roles and responsibilities of the dam owner and response agencies are defined.	X						DEP has been prepared.
3.7	Inundation maps and critical flood information are appropriate and are available to downstream response agencies.	X						Inundation study has been undertaken and inundation maps are to be included in the DEP.
3.8	Exercises are carried out regularly to test the emergency procedures.			X			NCp	No documentation that exercises have been undertaken was provided.
3.9	Staff are adequately trained in the emergency procedures.			X			NCi	No documentation that staff have been undertaken training was provided.
3.10	Emergency plans are updated regularly and updated pages are distributed to all plan holders in a controlled manner.	X						The EPP was prepared in 2010, and updated in 2016 and 2017. DEP has been updated as part of this study.
4 Dam Safety Review								
4.1	A safety review of the dam ("Dam Safety Review") is carried out periodically based on the consequences of failure.	X						RDOS commissioned a DSR in 2010 and this dam safety review in 2020. Another Dam Safety Review should be conducted in ten years (2030), however RDOS should endeavor to implement the recommendations of this review before that time.

	DAM SAFETY EXPECTATIONS	Yes	N/A	No	Deficiencies		Non-conformances	Comments
					Actual	Potential		
5	Dam Safety Management System							
5.1	The dam safety management system for the dam is in place incorporating:							
a.	policies,	X						
b.	responsibilities,	X						
c.	plans and procedures including OMS, public safety and security,			X			NCp	Public safety and security plans not in place. 2019 "Risk Control Survey" has been completed but no evidence of implementation of recommended measures yet.
d.	documentation,	X						
e.	training and review,			X			NCp	No available documentation provided to show if regular dam safety training is provided to the inspector(s).
f.	prioritization and correction of deficiencies and non-conformances,	X						Prioritization and corrections of deficiencies and non-conformances are documented in this Dam Safety Review.
g.	supporting infrastructure			X			NCs	No instrumentation installed in dam and seepage monitoring.
5.2	Deficiencies are documented, reviewed and resolved in a timely manner. Decisions are justified and documented	X						Deficiencies are documented in this Dam Safety Review. Recommendations from the previous Dam Safety Review by EBA in 2010 have been partially implemented to date.
5.3	Applicable regulations are met	X						

13. Conclusions and Recommendations

A systematic Dam Safety Review has been performed for Elinor Lake South Dam in accordance with the current B.C. Water Sustainability Act and the B.C. Dam Safety Regulation [Reg. 44/2016] and the current Canadian Dam Association Dam Safety Guidelines. This DSR confirms that the reservoir and its water retaining structures are being operated and maintained in a generally safe condition; however, there are some notable dam safety deficiencies that require further investigation and action.

Deficiencies have been identified throughout the document and are tabulated along with their prioritization. The tables of issues and recommendations are provided in Table 13-1.

Recommended actions in the table for each issue are outlined; these represent the controls that can be implemented to mitigate the hazards. The actual and potential deficiencies were given an overall priority rating of the risks, defined as high, medium and low, based upon the potential of the issue leading to a critical failure of the structure. The actual or potential deficiencies are summarized in Table 13-1. The non-conformances were assigned a ranking of low, medium or high based on how they impact dam safety. Priority definitions are as follows:

- High:** Potential failure mode(s) are judged to present serious risks, either due to a high probability of failure or due to very high potential incremental damages, which justify an urgency in actions to reduce risk.
- Medium:** Potential failure mode(s) appear to be dam safety deficiencies that appear to indicate a potential concern, and actions are needed to better define risks or to reduce risks. Ensure routine risk management activities are in place. For those actions for which the case has been built to proceed before the next comprehensive review, take appropriate interim measures and schedule other actions as appropriate. Prioritize investigations to support justification for remediation and remediation design, as appropriate.
- Low:** Potential failure mode(s) at the facility do not appear to present significant risks. Determine whether action can wait until after the next comprehensive review of the dam and appurtenant structures. Continue routine dam safety risk management activities, normal operation, and maintenance.

The various action items are categorized based on areas of responsibility as Minor Improvements (Operations), Minor Capital Works (Engineering), or Major Capital Works (Capital). A budgetary level Class D cost estimate is included with notes on inclusions.

Table 13-1: Summary of Dam Safety Recommendations

Issue No.	Deficiency/Non-Conformance	Originator	Type	Status	Recommendation	Priority Rating	Cost Estimate - Type	Estimated Cost	Notes
ES-1	Dam classification – dam is currently classified as High consequence	FLNRO, 2019 2020 DSR	N/A	Resolved	The consequence classification should be reviewed annually in accordance with the BC Dam Safety Regulation, noting changes downstream of the dam.	Low	N/A		
ES-2a	Poor documentation currently exists of the dam construction and performance history, site-specific geotechnical information, embankment materials, among other details. There is one existing construction drawing showing a clay core. However, this has not been definitively confirmed. The 2010 DSR recommended a topographic survey of the dam (EBA, 2010). Lack of as-built information. Geotechnical information not available.	2010 DSR FLNRO, 2019 2020 DSR	NCi	Outstanding	If not already completed, a thorough review should be conducted for records related to design, construction and performance of the dam. In the absence of geotechnical data, detailed analyses of the dam's stability, and resilience against risks such as seepage and seismic events cannot be evaluated in detail.	Medium	Minor Improvements		
ES-2b		2010 DSR	NCi	Resolved	A topographic survey of the dam was completed in 2012.	N/A	N/A		
ES-2c		2020 DSR		Outstanding	A geotechnical investigation should be conducted to provide necessary input for further engineering analyses. The investigation should consist of test pits and boreholes at the dam crest to attempt to locate and characterize the material zones of the dam, if present. Laboratory and in-situ testing should be conducted to determine the material properties. Piezometers should be installed during investigation.	High	Minor Capital Works	\$41,000.00	Split with EN-2c
ES-2d	Lack of instrumentation.	2020 DSR	NCi,s	Outstanding	Piezometer(s) should be installed with the borehole drilling to enable continued monitoring of the pore water pressure conditions within the dam.	High	Minor Capital Works		Included in estimate for ES-2c
ES-3	There is currently no ability to measure quantity of seepage in areas where seepage has been observed historically.	2010 DSR 2020 DSR	NCi,s	Outstanding	Install or reinstate the weir at the outlet of the drain to allow for quantitative measurement of seepage flows.	Medium	Minor Capital Works	\$6,000.00	1 weir
ES-4	Evidence of seepage was observed at the downstream toe. However, heavy vegetation limited access to the area where seepage was observed.	2010 DSR FLNRO, 2019 2020 DSR	NCs	Outstanding	Extend limits of vegetation clearing downstream of the dam to allow for inspection of the toe and regular seepage observations.	Medium	Minor Improvements		
ES-5	A detailed geotechnical assessment could not be completed due to the absence of construction documentation and site-specific geotechnical data. The dam is potentially susceptible to failure modes including slope instability, piping, and liquefaction.	2010 DSR 2020 DSR	NCi	Outstanding	Geotechnical assessments should be undertaken upon completion of the recommended geotechnical investigation. These should evaluate risks of common failure modes including seismic and normal slope stability, piping, and liquefaction. It is expected that the results of these assessments may lead to a recommendation for construction of a toe berm or similar improvements to limit seepage and increase the stability of the dam at the downstream toe. In addition, internal stability assessment of dam core and filter compatibility assessment should be conducted.	High	Minor Capital Works	\$40,000.00	The design of potential improvements up to preliminary stage.
ES-6	The risk of piping failure was found to be in the unacceptable risk zone as outlined by the CDA Guidelines (EBA, 2010)	2010 DSR	NCi, An	Outstanding	The risk level remains similar to the previous assessment. The recommendations above to complete a geotechnical investigation and improve seepage monitoring and instrumentation can contribute to reducing the risk of piping failure.	Medium	Minor Capital Works		Included in estimate for ES-2c
ES-7	Topographic survey data from 2012 shows the dam crest elevation is lower than the design elevation of El. 1278 m (EBA, 2013). However, freeboard requirements are met according to CDA.	2010 DSR FLNRO, 2019 2020 DSR	NCm	Outstanding	Place material to re-grade the crest to the design/typical elevation to provide additional freeboard, in line with FLNRO Plan Submission Requirements for the Construction and Rehabilitation of Small Dams.	Medium	Minor Capital Works	\$15,000.00	

Issue No.	Deficiency/Non-Conformance	Originator	Type	Status	Recommendation	Priority Rating	Cost Estimate - Type	Estimated Cost	Notes
ES-8	Security/access issues leading to damage on dam crest and face from ATV traffic. Recent inspections also note damage by cattle and vehicles.	2010 DSR FLNRO, 2019 Risk Survey, 2020 DSR	NCp	Outstanding	Review security and access protocols and implement appropriate restrictions including those recommended in the 2019 Risk Control Study (Precise Services, 2019) to prevent damage or vandalism.	High	Minor Improvements	\$10,000.00	
ES-9	No Operations, Maintenance and Surveillance (OMS) manual was prepared for the dam as of the previous Dam Safety Review	2010 DSR	-	Resolved	An OMS manual has been published since the previous review (RDOS, 2017). The contents of the OMS were reviewed and revised as part of the 2020 review.	N/A			
ES-10	Dam Safety Review schedule	2020 DSR		New	In accordance with the High consequence classification, the next Dam Safety Review should be conducted in 2030, and every 10 years thereafter.	N/A	N/A		
ES-11	Dam Emergency Plan – the Emergency Preparedness Plan (EPP) should be updated to comply with the updated requirements for a Dam Emergency Plan (DEP) in the Dam Safety Regulation	FLNRO, 2019	-	Resolved	The Dam Emergency Plan has been updated as part of this review.	N/A			
ES-12	Lack of sufficient instrumentation and data assessment for performance monitoring	2020 DSR	Nci,s	New	The instrumentation monitoring shall include continuous records, plotting, and interpretation of seepage flow quantities against reservoir elevation. The piezometer information should be closely monitored once available.	Medium	N/A		
ES-13	Currently no riprap or erosion protection layer on the dam crest or upstream slope.	2020 DSR	NCm	New	Provide appropriately sized armour protection along the upstream face of the dam from the crest to 1 m below the low water level.	Low	Minor Capital Works		
ES-14	LLO structure is unprotected from vandalism and accidental damage from ATVs or other traffic at dam crest.	2020 DSR	NCm	New	Provide protection to the screw stem by adding bollards or a steel cover to prevent damage from ATV traffic.	Low	Minor Capital Works	\$ 5,000.00	
All-1	OMS could be improved by including supporting confirmation that highlighted maintenance activities are being completed.	2020 DSR	NCs	New	Regular verification of the completion of maintenance items recorded in the weekly site surveillance form would further support that maintenance items are being completed.	Low	Minor Improvements		
All-2	OMS does not have a table with positions and associated names describing roles and responsibilities.	2020 DSR	NCo	New	Update table in OMS to include positions and associated names describing roles and responsibilities.	Medium	Minor Improvements		
All-3	Routine Dam Inspection Report format does not contain all aspect of BC Dam Safety Office's Site Surveillance Form for weekly inspections.	2020 DSR	NCp	New	Routine Dam Inspection Report format should be improved to more closely follow the BC Dam Safety Site Surveillance Form for weekly inspections.	Low	Minor Improvements		
All-4	No formal Dam Safety Policy is in place for their dam safety program.	2020 DSR	NCp	New	The RDOS appears to be meeting the intent of a dam safety management system and should continue to improve and develop their system and adopt a formal policy statement on Dam Safety for their program to satisfy the CDA Dam Safety Guidelines. This will demonstrate a commitment to the regulation and provide a reason to perform necessary works.	Medium	Minor Improvements		
All-5	OMS could be improved by including more information to assist Dam Safety inspectors in detecting and responding to an emergency situation.	2020 DSR	NCp	New	In the OMS, inflow forecasting should include alarm limits on what scenario of Snow Survey combined with reservoir levels would create a need for action. Actions to be taken should be described. Any recommended drawdown in anticipation of large spring runoff events should also be documented.	Medium	Minor Improvements		

Issue No.	Deficiency/Non-Conformance	Originator	Type	Status	Recommendation	Priority Rating	Cost Estimate - Type	Estimated Cost	Notes
All-6	Emergency notification systems to alert the public should be expanded to include a text message template to facilitate public notification in the event of an emergency.	2020 DSR	NCp	New	It is recommended that the RDOS emergency call alert system, CivicReady be setup to allow for public signup in order to receive external text message notifications during an emergency.	Medium	Minor Improvements		
All-7	No available documentation provided to show if regular dam safety training is provided to the inspector(s).	2010 DSR, 2020 DSR	NCs	Outstanding	RDOS staff responsible for the DEP should regularly attend BC Dam Safety Dam Management seminars on dam safety and inspections (understood to be provided annually in most areas of BC, including Penticton). Records of attendance at these inspection workshops should be documented along with information on any additional training completed. This could include review of material provided on BC Dam Safety website.	Medium	Minor Improvements		
All-8	No available documentation to show that exercises are carried out regularly to test the emergency procedures.	2020 DSR	NCp	New	Provide documented training to staff in emergency procedures, and carry out and document regular exercises to test the emergency procedures. Follow additional recommendations in proposed new Dam Emergency Plan (DEP) procedure.	Medium	Minor Improvements		

Note that Issues No's are categorized as either "ES" (Elinor South) or "All" (indicating similar OMS related issues that span all of the Naramata Dams).

14. References

- Abrahamson BT and Pentland RS. 2010. Probable Maximum Flood Estimator for British Columbia. Agriculture and Agri-Food Canada (AAFC).
- B.C. Reg 44/2000. 2000. Water Act - British Columbia Dam Safety Regulation.
- B.C. Reg 40/2016, 2016, "Water Sustainability Act, Dam Safety Regulation", 2016.
- B.C. Ministry of Forests, Lands, Natural Resource Operations and Rural Development (FLNRO). 2018. Dam Safety Program. Plan Submission Requirements for the Construction and Rehabilitation of Small Dams.
- Big Meadow Lake Dam Site Photos. 2010.
- British Columbia Department of Lands, Forests and Water Resources – Water Rights Branch. Drawing: "Big Meadow Reservoir Plan of Storage". 8 April 1963.
- British Columbia Department of Lands, Forests and Water Resources – Water Rights Branch. Drawing: "Big Meadow Dam – Details of Repairs to Culvert Gate & Outlet". 19 September 1966.
- British Columbia Department of Lands, Forests and Water Resources – Water Rights Branch. Drawing: "Eleanor & Naramata Lakes – Plan of Storage". 17 April 1964.
- British Columbia Department of Lands, Forests and Water Resources – Water Rights Branch. Drawing: "Eleanor Lake Dam – Details of Culvert Gate Repairs". December 1966.
- British Columbia Department of Lands, Forests and Water Resources – Mapping Branch. Mapping: "Naramata Creek Watershed Area – Map 5: Groundwater Sensitivity Zones". 21 December 1998.
- British Columbia Ministry of Environment – Inventory and Engineering Branch. Drawing: "Big Meadow Lake Reservoir – Plan of Reservoir". March 1982
- British Columbia Ministry of Environment, Lands and Parks - Water Management Division. "Naramata Fan Study (with Robinson and Chute Creeks)". December 1994
- Canadian Dam Association (CDA). 2011. Guidelines for Public Safety Around Dams.
- Canadian Dam Association (CDA). 2013a. Dam Safety Guidelines 2007 (2013 Revision).
- Canadian Dam Association (CDA). 2013b. Seismic Hazard Considerations for Dam Safety 2007 Dam Safety Guidelines, Canadian Dam Association, 2013 Revision.
- EBA Engineering Consultants. "Big Meadow Lake Dam Geotechnical Assessment". 11 January 2013.
- EBA Engineering Consultants. "Dam Safety Review – Big Meadow Lake Dam". 17 December 2010.

EBA Engineering Consultants. "Dam Safety Review – Naramata Lake Dam". 17 December 2010.

EBA Engineering Consultants. "Dam Safety Review Summary Report – Naramata Dams". 21 December 2010.

EBA Engineering Consultants. "Dam Safety Reviews for Elinor Lake North (Saddle) Dam and Elinor Lake South Dam". 17 December 2010.

EBA Engineering Consultants. "Hydrotechnical Assessment of the Naramata Dams". 20 December 2010.

EBA Engineering Consultants. Memo: "Topographical Survey of Naramata Dams". 10 January 2013.

EGBC. 2016. Legislated Dam Safety Reviews in BC. Professional Practice Guidelines. V3.0.
Elinor Lake Dams Site Photos. 2010.

Foster M., Fell R., Spannagle M., 2000. A Method for Assessing the Relative Likelihood of Failure of Embankment Dams by Piping, Canadian Geotechnical Journal, 37: 1025-1061.

Garner SJ and Fannin RJ. 2010 Understanding Internal Erosion: A decade of research following a sinkhole event. International Journal on Hydropower and Dams 17(3):93-98 · January 2010.

ICOLD (International Commission On Large Dams). 2017. Internal Erosion of Existing Dams, Levees, and Dikes. Bulletin 164.

Kelowna Regional Office – Water Rights Branch. "Eleanor Lake Reservoir – Storage Capacity Table". 17 August 1979.

Ministry of Forests, Lands, Natural Resource Operations and Rural Development (FLNRO RD). 2018. Plan Submission Requirements for the Construction and Rehabilitation of Small Dams.

Naramata Irrigation District. Drawing: "Improvements – South and North Intakes". 6 December 1979.

Naramata Irrigation District. "Naramata Lake Operation and Maintenance Manual". April 1993.

Naramata Lake Dam Site Photos. 2010.

Okanagan Survey & Design Ltd. Mapping: "Elinor Lake – North Dam Site Topography". 24 July 2012.

Okanagan Survey & Design Ltd. Mapping: "Elinor Lake – South Dam Site Topography". 24 July 2012.

Okanagan Survey & Design Ltd. Mapping: "Naramata Lake Dam – Site Topography". 24 July 2012.

Precise Services. "Risk Control Survey". 2019

Regional District of Okanagan-Similkameen. "Elinor Lake Reservoir and Dams Operation, Maintenance and Surveillance Plan Emergency Preparedness Plan". May 2017.

Regional District of Okanagan-Similkameen. "Naramata Uplands Waterworks (Diversion, Divide, Flume, Highline & Intakes - Maintenance and Surveillance Plan". April 2013.

Regional District of Okanagan-Similkameen. "Naramata Water System North and South Creek Intake Photos". 12 March 2020.

Stanley Associates Engineering Ltd. Drawing: "Chute Lake Diversion – Existing Structure". October 1993.

Various. Drawing: "Naramata Lake Historical Drawings". 1967 – 1978.

Canadian Dam Association, Technical Bulletin: Dam Safety Reviews, 2016.

OPTA Precise Services LP, "Risk Control Survey: Municipal Insurance Association of British Columbia". July 2019.

USBR. 1989. Design standards no. 13 — embankment dams. United States Bureau of Reclamation, United States Department of the Interior, Denver, Colo.

Appendix A

Site Visit Photo Report



Photo A1: Elinor Lake South Dam Upstream Slope and Crest, Looking from Right Abutment



Photo A2: Elinor Lake South Dam upstream slope, Looking from Right Abutment



Photo A3: Elinor Lake South Dam Upstream Slope and Left Abutment



Photo A4: Elinor Lake South Dam Upstream slope, Left abutment, and Log Boom



Photo A5: Elinor Lake South Dam Downstream Slope and Outlet Works



Photo A6: Elinor Lake South Dam Outlet Works, Tailrace Channel, Seepage on Right of Structure



Photo A7: Elinor Lake South Dam, Outlet Structure



Photo A8: Elinor Lake South Dam Downstream Pond, left of Outlet Structure



Photo A9: Elinor Lake South Dam, Dead Trees Stored at the Dam Toe



Photo A10: Elinor Lake South Dam, Public Safety Sign



Photo A11: Elinor Lake South Dam, Spillway Seal Structure



Photo A12: Elinor Lake South Dam, Spillway Channel, Downstream Area



Photo A13: Elinor Lake South Dam, Spillway Channel, Upstream Area



Photo A14: Elinor Lake South Dam, Log Boom



Photo A15: Elinor Lake South Dam, Spillway Channel and Areas on Left Abutment

Appendix B

Seismic Hazard Characterization

2015 National Building Code Seismic Hazard Calculation

INFORMATION: Eastern Canada English (613) 995-5548 français (613) 995-0600 Facsimile (613) 992-8836
Western Canada English (250) 363-6500 Facsimile (250) 363-6565

Site: 49.667N 119.537W

User File Reference: Naramata Dam Sites

2021-01-06 18:11 UT

Requested by: Tim Tuo, Hatch Ltd.

Probability of exceedance per annum	0.000404	0.001	0.0021	0.01
Probability of exceedance in 50 years	2 %	5 %	10 %	40 %
Sa (0.05)	0.081	0.049	0.032	0.011
Sa (0.1)	0.119	0.071	0.046	0.015
Sa (0.2)	0.151	0.095	0.064	0.025
Sa (0.3)	0.148	0.098	0.069	0.029
Sa (0.5)	0.130	0.089	0.064	0.028
Sa (1.0)	0.097	0.066	0.046	0.020
Sa (2.0)	0.067	0.043	0.030	0.012
Sa (5.0)	0.030	0.017	0.011	0.004
Sa (10.0)	0.010	0.006	0.004	0.002
PGA (g)	0.070	0.044	0.029	0.010
PGV (m/s)	0.124	0.078	0.051	0.020

Notes: Spectral ($S_a(T)$, where T is the period in seconds) and peak ground acceleration (PGA) values are given in units of g (9.81 m/s^2). Peak ground velocity is given in m/s . Values are for "firm ground" (NBCC2015 Site Class C, average shear wave velocity 450 m/s). NBCC2015 and CSAS6-14 values are highlighted in yellow. Three additional periods are provided - their use is discussed in the NBCC2015 Commentary. Only 2 significant figures are to be used. **These values have been interpolated from a 10-km-spaced grid of points. Depending on the gradient of the nearby points, values at this location calculated directly from the hazard program may vary. More than 95 percent of interpolated values are within 2 percent of the directly calculated values.**

References

National Building Code of Canada 2015 NRCC no. 56190; Appendix C: Table C-3, Seismic Design Data for Selected Locations in Canada

Structural Commentaries (User's Guide - NBC 2015: Part 4 of Division B)
Commentary J: Design for Seismic Effects

Geological Survey of Canada Open File 7893 Fifth Generation Seismic Hazard Model for Canada: Grid values of mean hazard to be used with the 2015 National Building Code of Canada


See the websites www.EarthquakesCanada.ca and www.nationalcodes.ca for more information

Appendix C

Seepage Analysis Results

Color	Name	Category	Kind	Parameters
Blue	1- US Head : FSL 1276.55	Hydraulic	Water Total Head	1,276.55 m
Cyan	3-Potential Seepage face	Hydraulic	Water Flux	0 m/sec


Color	Name	Model	Vol. WC. Function	K-Function	Ky'/Kx' Ratio	Rotation (°)
Orange	Clay Core	Saturated / Unsaturated	Generic	Clay/Silt, Ksat = 2.5e-08 m/s	1	0
Yellow	Foundation - Sandy Till	Saturated / Unsaturated	Generic	ND - Foundation Sandy Till	1	0
Light Green	Shell Fill	Saturated / Unsaturated	Generic	ND - Shell Fill	1	0



Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Seepage Analysis – Model Geometry	
Analysis By	T. Tuo	Output	Model Geometry
Date	11/01/2021	Report No.	H362819

Color	Name	Category	Kind	Parameters
Blue	1- US Head : FSL 1276.55	Hydraulic	Water Total Head	1,276.55 m
Cyan	3-Potential Seepage face	Hydraulic	Water Flux	0 m/sec


Color	Name	Model	Vol. WC. Function	K-Function	Ky'/Kx' Ratio	Rotation (°)
Orange	Clay Core	Saturated / Unsaturated	Generic	Clay/Silt, Ksat = 2.5e-08 m/s	1	0
Yellow	Foundation - Sandy Till	Saturated / Unsaturated	Generic	ND - Foundation Sandy Till	1	0
Light Green	Shell Fill	Saturated / Unsaturated	Generic	ND - Shell Fill	1	0




Project	Elinor Lake South Dam – Dam Safety Review		
Analysis Description	Seepage Analysis: Steady State Condition – Full Supply Level		
Analysis By	T. Tuo	Output	Steady State Phreatic Surface
Date	11/01/2021	Report No.	H362819

Color	Name	Category	Kind	Parameters
Blue	1- US Head : FSL 1276.55	Hydraulic	Water Total Head	1,276.55 m
Cyan	3-Potential Seepage face	Hydraulic	Water Flux	0 m/sec

Color	Name	Model	Vol. WC. Function	K-Function	Ky'/Kx' Ratio	Rotation (°)
Orange	Clay Core	Saturated / Unsaturated	Generic	Clay/Silt, Ksat = 2.5e-08 m/s	1	0
Yellow	Foundation - Sandy Till	Saturated / Unsaturated	Generic	ND - Foundation Sandy Till	1	0
Light Green	Shell Fill	Saturated / Unsaturated	Generic	ND - Shell Fill	1	0




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Seepage Analysis: Steady State Condition – Full Supply Level	
Analysis By	T. Tuo	Output	Water Total Head (m)
Date	11/01/2021	Report No.	H362819



Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Seepage Analysis: Steady State Condition – Full Supply Level	
Analysis By	T. Tuo	Output	Toe Exit Gradients
Date	11/01/2021	Report No.	H362819

Color	Name	Category	Kind	Parameters
■	1- US Head : IDF 1277.10	Hydraulic	Water Total Head	1,277.1 m
■	3-Potential Seepage face	Hydraulic	Water Flux	0 m/sec


Color	Name	Model	Vol. WC. Function	K-Function	Ky'/Kx' Ratio	Rotation (°)
■	Clay Core	Saturated / Unsaturated	Generic	Clay/Silt, Ksat = 2.5e-08 m/s	1	0
■	Foundation - Sandy Till	Saturated / Unsaturated	Generic	ND - Foundation Sandy Till	1	0
■	Shell Fill	Saturated / Unsaturated	Generic	ND - Shell Fill	1	0



Project	Elinor Lake South Dam – Dam Safety Review		
Analysis Description	Seepage Analysis: Steady State Condition – Inflow Design Flood		
Analysis By	T. Tuo	Output	Steady State Phreatic Surface
Date	11/01/2021	Report No.	H362819

Color	Name	Category	Kind	Parameters
■	1- US Head : IDF 1277.10	Hydraulic	Water Total Head	1,277.1 m
■	3-Potential Seepage face	Hydraulic	Water Flux	0 m/sec


Color	Name	Model	Vol. WC. Function	K-Function	Ky'/Kx' Ratio	Rotation (°)
■	Clay Core	Saturated / Unsaturated	Generic	Clay/Silt, Ksat = 2.5e-08 m/s	1	0
■	Foundation - Sandy Till	Saturated / Unsaturated	Generic	ND - Foundation Sandy Till	1	0
■	Shell Fill	Saturated / Unsaturated	Generic	ND - Shell Fill	1	0



Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Seepage Analysis: Steady State Condition – Inflow Design Flood	
Analysis By	T. Tuo	Output	Water Total Head (m)
Date	11/01/2021	Report No.	H362819

Water XY-Gradient

- 0 - 0.05
- 0.05 - 0.1
- 0.1 - 0.15
- 0.15 - 0.2
- 0.2 - 0.25
- 0.25 - 0.3
- 0.3 - 0.35
- 0.35 - 0.4
- 0.4 - 0.45
- 0.45 - 0.5
- 0.5 - 0.55
- 0.55 - 0.6
- 0.6 - 0.65
- 0.65 - 0.7
- 0.7 - 0.75
- 0.75 - 0.8
- 0.8 - 0.85
- 0.85 - 0.9
- 0.9 - 0.95




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Seepage Analysis: Steady State Condition – Inflow Design Flood	
Analysis By	T. Tuo	Output	Toe Exit Gradients
Date	11/01/2021	Report No.	H362819

Appendix D


Slope Stability Analysis Results

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
Orange	Clay Core	Mohr-Coulomb	18	0	28	0	1
Yellow	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
Light Green	Shell Fill	Mohr-Coulomb	20	0	33	0	1




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis – Model Geometry	
Analysis By	T. Tuo	Output	Model Geometry
Date	11/01/2021	Report No.	H362819

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
	Clay Core	Mohr-Coulomb	18	0	28	0	1
	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
	Shell Fill	Mohr-Coulomb	20	0	33	0	1




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis: LC-1 – Normal Load Condition – Full Supply Level	
Analysis By	T. Tuo	Slope	Upstream
Date	11/01/2021	Report No.	H362819

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
Orange	Clay Core	Mohr-Coulomb	18	0	28	0	1
Yellow	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
Green	Shell Fill	Mohr-Coulomb	20	0	33	0	1




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis: LC-1 – Normal Load Condition – Full Supply Level	
Analysis By	T. Tuo	Slope	Downstream
Date	11/01/2021	Report No.	H362819

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
Orange	Clay Core	Mohr-Coulomb	18	0	28	0	1
Yellow	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
Light Green	Shell Fill	Mohr-Coulomb	20	0	33	0	1




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis: LC-2 – Flood Load Condition – Inflow Design Flood	
Analysis By	T. Tuo	Slope	Upstream
Date	11/01/2021	Report No.	H362819

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
Orange	Clay Core	Mohr-Coulomb	18	0	28	0	1
Yellow	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
Green	Shell Fill	Mohr-Coulomb	20	0	33	0	1




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis: LC-2 – Flood Load Condition – Inflow Design Flood	
Analysis By	T. Tuo	Slope	Downstream
Date	11/01/2021	Report No.	H362819

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
	Clay Core	Mohr-Coulomb	18	0	28	0	1
	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
	Shell Fill	Mohr-Coulomb	20	0	33	0	1




Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis: LC-3 – Rapid Draw Down – From Full Supply Level	
Analysis By	T Singh	Slope	Upstream
Date	11/01/2021	Report No.	H362819

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
Orange	Clay Core	Mohr-Coulomb	18	0	28	0	1
Yellow	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
Light Green	Shell Fill	Mohr-Coulomb	20	0	33	0	1



Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis: LC-4 – Seismic Condition – Full Supply Level	
Analysis By	T Singh	Slope	Upstream
Date	11/01/2021	Report No.	H362819

Color	Name	Model	Unit Weight (kN/m ³)	Cohesion' (kPa)	Phi' (°)	Phi-B (°)	Piezometric Line
Orange	Clay Core	Mohr-Coulomb	18	0	28	0	1
Yellow	Foundation - Sandy Till	Mohr-Coulomb	21	0	32	0	1
Green	Shell Fill	Mohr-Coulomb	20	0	33	0	1



Project		Elinor Lake South Dam – Dam Safety Review	
Analysis Description		Slope Stability Analysis: LC-4 – Seismic Condition – Full Supply Level	
Analysis By	T. Tuo	Slope	Downstream
Date	11/01/2021	Report No.	H362819

Appendix E

Dam Safety Review Assurance Statement

Dam Safety Review Assurance Statement

Note: This statement is to be read and completed in conjunction with the current APEGBC Professional Practice Guidelines – Legislated Dam Safety Reviews in British Columbia, (“APEGBC Guidelines”) and is to be provided for dam safety review reports for the purposes of the Dam Safety Regulation, BC Reg. 40/2016 as amended. Italicized words are defined in the APEGBC Guidelines.

To: The *Owner(s)*

Date: February 25, 2021

Regional District of Okanagan-Similkameen

Name

101 Martin Street, Penticton, BC, V2A 5J9

Address

With reference to the Dam Safety Regulation, B.C. Reg. 40/2016 as amended.

For the dam:

UTM (Location):	Elinor Lake South Dam:49.6632 North, 119.5373 West
Located at (Description):	North to south trending valley, approximately 8.4 km to the northeast of the Naramata Township.
Name of dam or description:	Elinor Lake South Dam
Provincial dam number:	Elinor Lake South Dam:
Dam function:	Maintaining essential creek flows, emergency backup supply of water and supplying irrigation water to agricultural lands
Owned by: (the “Dam”)	Regional District of Okanagan-Similkameen

Current Dam classification is:

Check one

- Low
- Significant
- High
- Very High
- Extreme

The undersigned hereby gives assurance that he/she is a Qualified Professional Engineer.

I have signed, sealed and dated the attached dam safety review report on the Dam in accordance with the APEGBC Guidelines. That report must be read in conjunction with this Statement. In preparing that report I have:

Check to the left of applicable items (see Guideline Section 3.2):

- ✓ 1. Collected and reviewed available and relevant background information, documentation and data.
- ✓ 2. Understood the current classification for the Dam, including performance expectations.
- ✓ 3. Undertaken an initial facility review.
- ✓ 4. Reviewed and assessed the Dam safety management obligations and procedures.
- ✓ 5. Reviewed the condition of the Dam, reservoir and relevant upstream and downstream portions of the river.
- ✓ 6. Interviewed operations and maintenance personnel.
- ✓ 7. Reviewed available maintenance records, the Operations, Maintenance and Surveillance (OMS) Manual and the Dam Emergency Plan (DEP).
- ✓ 8. Confirmed proper functioning of flow control equipment.
- ✓ 9. After the above, reassess the consequence classification, including the identification of required dam safety criteria.
- ✓ 10. Carried out a dam safety analysis based on the classification in 9. Above.
- ✓ 11. Evaluated facility performance.
- ✓ 12. Identified, characterized and determined the severity of deficiencies in the safe operation of the Dam and non-conformances in dam safety management system.
- ✓ 13. Recommended and prioritized actions to be taken in relation to deficiencies and non-conformances.
- ✓ 14. Prepared a dam safety review report for submittal to the Regulatory Authority by the Owner and reviewed the report with the Owner.
- ✓ 15. The dam safety review report has been reviewed in meeting the intent of APEGBC Bylaw 14(b)(2).

Based on my dam safety review, the current dam classification is:

Check one

- Appropriate
- Should be reviewed and amended

I undertook the following type of dam safety review:

Check one

- Audit
- Comprehensive
- Detailed design-based multi-disciplinary
- Comprehensive, detailed design and performance

I hereby give my assurance that, based on the attached dam safety review report, at this point in time:

Check one

- The Dam is reasonably safe in that the dam safety review did not reveal any unsafe or unacceptable conditions in relation to the design, construction, maintenance and operation of the Dam as set out in the attached dam safety review report
- The Dam is reasonably safe but the dam safety review did reveal non-conformances with the Dam Safety Regulation as set out in section(s) ___ of the attached dam safety review report.
- The Dam is reasonably safe but the dam safety review did reveal deficiencies and non-conformances as set out in section(s) ___12___ of the attached dam safety review report.
- The Dam is not safe in that the dam safety review did reveal deficiencies and/or non-conformances which require urgent action as set out in section(s) ___ of the attached dam safety review report.

Name: David Bonin P.Eng. (Dam Safety/Hyrotechnical)
Shayla Murphy P.Eng. (Hyrotechnical)
Parham Ashayer P.Eng. (Geotechnical)
Amit Pashan P.Eng. (Structural)

Date: February 25, 2021

Signatures: _____




Address: 1066 W Hastings St., Suite 400,
Vancouver, BC, V6E 3X2

Telephone: (604) 689-5767

(Affix Professional Seals here)

If the Qualified Professional Engineer is a member of a firm, complete the following:

I am a member of the firm _____ Hatch Ltd.
and I sign this letter on behalf of the firm. (Print name of firm)